




report date: 2024-03-29

General information

Make	VOLVO
Model	V70 V70 140
Colour	Silver
Year of manufacture	2002
Top speed	121 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	142 BHP
Max. torque	206 Nm at 3.600 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	19.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	27.4 mpg
CO2 emission	222 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-06
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-23
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	37
Total items failed	26

MOT #25	2023-01-24 11:47
MOT test number	934922900923
Result	✓ Passed
Next expiry date	2024-01-23
Advice	Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #24	2023-01-23 12:22
MOT test number	168690642426
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Front Windscreen washer not working (3.5 (a))
Advice	Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

MOT #23	2022-02-28 09:59
MOT test number	273469087888
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #22** 2021-02-17 13:54**MOT test number** 497699239899**Result** ✓ Passed**MOT #21** 2020-02-19 15:20**MOT test number** 639110430784**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Exhaust mounting defective (6.1.2 (a))**MOT #20** 2020-02-18 14:07**MOT test number** 959240188792**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn wishbone bush (5.3.4 (a) (i))**Fail** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Exhaust mounting defective (6.1.2 (a))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #19** 2019-02-04 16:47**MOT test number** 723044334125**Result** ✓ Passed**Advice** Offside front tyre worn on inner edge

**MOT #18** 2019-02-01 18:43**MOT test number** 867640405219**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside front tyre worn on inner edge**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #17** 2018-02-28 16:04**MOT test number** 628062107790**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Plastic sill covers fitted making sill examination impossible

**MOT #16**

2018-02-19 13:29

MOT test number

589682235312

Result**✗ Failed**

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Nearside Front Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Plastic sill covers fitted making sill examination impossible
- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Power steering malfunctioning (2.3.3a)
- Fail** Offside Rear fog lamp not working (1.3.2b)
- Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #15

2017-01-24 16:41

MOT test number

137736293128

Result**✓ Passed**

- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Exhaust rear hanger corroded
- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #14**

2017-01-23 17:01

MOT test number

986255709915

Result**✗ Failed**

Advice Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Fail Offside Headlamp aim too high (1.8)

Advice Exhaust rear hanger corroded

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #13

2016-02-04 15:55

MOT test number

394530245483

Result**✓ Passed**

Advice Direction indicators slightly discoloured (1.4.A.2f)

**MOT #12** 2016-02-01 14:59**MOT test number** 943838778508**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Fuel cap/sealing device sealing washer deteriorated (7.2.4c)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Direction indicators slightly discoloured (1.4.A.2f)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #11** 2015-01-29 10:57**MOT test number** 696589925081**Result** ✓ Passed**MOT #10** 2014-02-06 13:11**MOT test number** 865237534094**Result** ✓ Passed**MOT #9** 2013-02-07 15:51**MOT test number** 218168833022**Result** ✓ Passed**MOT #8** 2012-02-15 15:41**MOT test number** 127866642022**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #7** 2011-02-08 15:41**MOT test number** 646859231046**Result** ✓ Passed**MOT #6** 2010-02-09 15:43**MOT test number** 614250540092**Result** ✓ Passed**MOT #5** 2009-02-23 12:13**MOT test number** 211574459055**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2008-02-15 10:00**MOT test number** 124806448094**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2008-02-15 10:00**MOT test number** 970996048068**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2007-02-16 10:52**MOT test number** 261687947037**Result** ✓ Passed



MOT #1	2006-02-21 15:10
MOT test number	144602556087
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 December 2022

✕
MOT

Expired:
23 January 2024

Tax status	Expired at 1 December 2022
Days left	516 days too late
MOT expiry date	23 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-02-12
Last registration	2023-01-24
Complete history	See info



Registration #1	2002-02-12	13 mi
Registration #2	2006-02-21	40.524 mi
Registration #3	2007-02-16	54.621 mi
Registration #4	2008-02-15	59.948 mi
Registration #5	2009-02-23	65.001 mi
Registration #6	2010-02-09	69.313 mi
Registration #7	2011-02-08	72.940 mi
Registration #8	2012-02-15	77.426 mi
Registration #9	2013-02-07	81.869 mi
Registration #10	2014-02-06	86.842 mi
Registration #11	2015-01-29	91.521 mi
Registration #12	2016-02-01	96.517 mi
Registration #13	2016-02-04	96.581 mi
Registration #14	2016-02-04	96.581 mi
Registration #15	2016-02-04	96.581 mi
Registration #16	2016-02-04	96.581 mi
Registration #17	2016-02-04	96.581 mi
Registration #18	2016-02-04	96.581 mi
Registration #19	2016-02-04	96.581 mi
Registration #20	2016-02-04	96.581 mi
Registration #21	2016-02-04	96.581 mi
Registration #22	2016-02-04	96.581 mi
Registration #23	2016-02-04	96.581 mi
Registration #24	2016-02-04	96.581 mi
Registration #25	2016-02-04	96.581 mi
Registration #26	2016-02-04	96.581 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1410 mm
Length	4720 mm

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	2543215