



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	FR-V VTEC SE
Colour	Red
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	154 Nm at 4.800 rpm
Engine capacity	1.668 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1	
Date	2021-05-27
Pictures	26
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2022-02-02
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	52
Total items failed	14

MOT #18	2021-02-03 13:42
----------------	------------------

MOT test number	361607094402
------------------------	--------------

Result	✓ Passed
---------------	----------

Next expiry date	2022-02-02
-------------------------	------------

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (2mm) (5.2.3 (e))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2021-02-02 11:00

MOT test number

540490033419

Result

✗ Failed

- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Windscreen washer not working (3.5 (a))
- Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (2mm) (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #16

2020-01-23 12:17

MOT test number

289785300217

Result

✓ Passed

MOT #15

2019-01-29 15:22

MOT test number

600967895141

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Underbody covered in underseal
- Advice** Front crossmember slightly surface rust
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #14**

2019-01-28 14:50

MOT test number

533048148341

Result**✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Underbody covered in underseal**Advice** Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front crossmember slightly surface rust**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #13**

2018-01-31 11:45

MOT test number

612737964179

Result**✓ Passed****Advice** General corrosion noticed and advice**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust has a minor leak of exhaust gases back box (7.1.2)

**MOT #12**

2017-02-01 12:14

MOT test number

534555696248

Result

✓ Passed

Advice Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Anti-roll bar has slight play in a ball joint both rear (2.4.G.2)**Advice** General corrosion noticed and advice**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11**

2017-02-01 12:14

MOT test number

236720956688

Result

✗ Failed

Pass with rectification Offside Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Anti-roll bar has slight play in a ball joint both rear (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** General corrosion noticed and advice**MOT #10**

2016-01-29 16:25

MOT test number

886357517244

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #9** 2016-01-29 11:44**MOT test number** 680323615408**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2015-01-20 11:58**MOT test number** 299150225010**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/r tyre inner wear.**Notice** N/s/f wiper deteriorated**Advice** Bonnet retaining device slightly deteriorated (8.4.2)**MOT #7** 2013-12-30 16:22**MOT test number** 698424263314**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #6** 2012-08-21 13:35**MOT test number** 468314432263**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-02-11 11:50**MOT test number** 225152441055**Result** ✓ Passed**MOT #4** 2010-02-11 11:20**MOT test number** 353252540094**Result** ✓ Passed**MOT #3** 2010-02-09 16:45**MOT test number** 721380340088**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Centre Exhaust system not adequately supported (7.1.1)**MOT #2** 2009-02-16 09:36**MOT test number** 194087549458**Result** ✓ Passed**Notice** All three wiper blade's in poor condition, advise replacment.



MOT #1	2008-02-14 12:26
MOT test number	860155948091
Result	✓ Passed



Tax & MOT check

×

Untaxed

Tax expired:
1 July 2021

×

MOT

Expired:
2 February 2022

Tax status

Expired at 1 July 2021

Days left

1034 days too late

MOT expiry date

2 February 2022

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-02-23
Last registration	2021-02-03
Complete history	See info



Registration #1	2005-02-23	29 mi
Registration #2	2008-02-14	21.218 mi
Registration #3	2009-02-16	28.118 mi
Registration #4	2010-02-09	34.400 mi
Registration #5	2010-02-11	34.400 mi
Registration #6	2011-02-11	42.402 mi
Registration #7	2012-08-21	53.923 mi
Registration #8	2013-12-30	66.123 mi
Registration #9	2015-01-20	77.404 mi
Registration #10	2016-01-29	87.063 mi
Registration #11	2016-05-20	95.577 mi
Registration #12	2016-05-20	95.577 mi
Registration #13	2016-05-20	95.577 mi
Registration #14	2016-05-20	95.577 mi
Registration #15	2016-05-20	95.577 mi
Registration #16	2016-05-20	95.577 mi
Registration #17	2016-05-20	95.577 mi
Registration #18	2016-05-20	95.577 mi
Registration #19	2016-05-20	95.577 mi
Registration #20	2016-05-20	95.577 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1397 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Engine number	D17A24301120