




report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO 2700 L1H1 CDTI P/V SPORTIVE ECOFLEX S/S
Colour	White
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.9 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-10-07
Pictures	1
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2021-10-05
Pictures	6
Listing price	View report



source: [cargurus.co.uk](#)





MOT history

MOT expiry date	2024-09-10
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #6 2023-09-11 13:05

MOT test number 581322947445

Result ✓ Passed

Next expiry date 2024-09-10

Advice Front Sub-frame pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))

Advice Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2022-09-09 16:40

MOT test number 612767762981

Result ✓ Passed

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #4 2021-09-10 14:31

MOT test number 629270821562

Result ✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #3**

2020-08-14 15:19

MOT test number

973720731924

Result

✓ Passed

Advice

Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

MOT #2

2020-08-14 09:33

MOT test number

332977624834

Result

✗ Failed

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #1

2019-09-05 10:19

MOT test number

522414220866

Result

✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge 205/65/16 105/107 T 2.40mm (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 205/65/16 105/107 T 1.98mm (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
10 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	10 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-08-17
Last registration	2023-09-11
Complete history	See info



Registration #1	2016-08-17	8 mi
Registration #2	2019-09-05	63.944 mi
Registration #3	2020-08-14	72.414 mi
Registration #4	2020-08-14	72.414 mi
Registration #5	2021-09-10	84.721 mi
Registration #6	2022-09-10	95.277 mi
Registration #7	2022-09-10	95.277 mi
Registration #8	2022-09-10	95.277 mi
Registration #9	2023-09-11	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1970 mm
Length	4998 mm
Kerb weight	1683 kg
Max. allowed weight	2760 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MB - C118686LWU