



report date: 2024-03-28

General information

Make	SUZUKI
Model	SPLASH SZ3
Colour	Turquoise
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 4.800 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-16
Pictures	25
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-13
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	3
Total items failed	4

MOT #14	2023-07-14 08:05
MOT test number	331771173502
Result	✓ Passed
Next expiry date	2024-07-13

MOT #13	2022-05-27 07:56
MOT test number	403377146834
Result	✓ Passed

MOT #12	2021-06-23 07:30
MOT test number	718455060589
Result	✓ Passed

MOT #11	2021-06-11 15:05
MOT test number	492083017956
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #10	2020-07-30 11:04
MOT test number	125433074269
Result	✓ Passed

Advice Rear Brake pipe corroded, covered in grease or other material pipes across back axle corroded (1.1.11 (c))

**MOT #9** 2020-07-30 08:25**MOT test number** 646481099511**Result** ✗ Failed

Advice Rear Brake pipe corroded, covered in grease or other material pipes across back axle corroded (1.1.11 (c))

Fail Nearside Front Suspension arm pin or bush excessively worn rearmost bush seperated from arm (5.3.4 (a) (i))

MOT #8 2019-07-31 12:31**MOT test number** 880068101367**Result** ✓ Passed**MOT #7** 2019-07-31 07:58**MOT test number** 615331752027**Result** ✗ Failed

Fail Offside Front Suspension arm pin or bush excessively worn rearmost bush split from arm (5.3.4 (a) (i))

MOT #6 2018-08-13 09:16**MOT test number** 110921467926**Result** ✓ Passed

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MOT #5 2017-08-24 14:36**MOT test number** 281451612952**Result** ✓ Passed**MOT #4** 2017-05-24 13:35**MOT test number** 396253997447**Result** ✓ Passed



MOT #3	2017-05-24 13:35
MOT test number	302249092412
Result	✗ Failed
<div>Pass with rectification</div> Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #2	2016-05-25 13:49
MOT test number	833466539599
Result	✓ Passed

MOT #1	2015-05-26 14:31
MOT test number	466156545138
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
13 July 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-05-31
Last registration	2023-07-14
Complete history	See info



Registration #1	2012-05-31	19 mi
Registration #2	2015-05-26	10.134 mi
Registration #3	2016-05-25	12.454 mi
Registration #4	2017-05-24	14.003 mi
Registration #5	2017-05-24	14.003 mi
Registration #6	2017-08-24	14.459 mi
Registration #7	2018-08-13	20.041 mi
Registration #8	2019-07-31	24.861 mi
Registration #9	2019-07-31	25.277 mi
Registration #10	2019-07-31	25.277 mi
Registration #11	2019-07-31	25.277 mi
Registration #12	2019-07-31	25.277 mi
Registration #13	2019-07-31	25.277 mi
Registration #14	2019-07-31	25.277 mi
Registration #15	2019-07-31	25.277 mi
Registration #16	2019-07-31	25.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1590 mm
Length	3775 mm
Wheel base	2360 mm
Kerb weight	1075 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K10B-1103189