



report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Grey
Year of manufacture	2009
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-20
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	46
Total items failed	9

MOT #17	2024-02-16 12:27
---------	------------------

MOT test number	466392516301
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-20
------------------	------------

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn smooth on inner edge & side wall scrubbed (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside registration plate lamp bulb poor light output
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn smooth on inner edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing low on inner edge (5.2.3 (e))
- Advice** Play in steering rack inner joint(s) offside & nearside

**MOT #16** 2024-02-14 16:31**MOT test number** 708878157652**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn smooth on inner edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing low on inner edge (5.2.3 (e))**Advice** Play in steering rack inner joint(s) offside & nearside**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt boot split (2.1.3 (g) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn smooth on inner edge & side wall scrubbed (5.2.3 (e))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside registration plate lamp bulb poor light output**MOT #15** 2023-02-17 12:32**MOT test number** 795065825539**Result** ✓ Passed**MOT #14** 2023-02-17 10:09**MOT test number** 139683397058**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage fractured broken (5.3.3 (b) (ii))**Advice** Rear Exhaust mounting defective hanger broken (6.1.2 (a))**MOT #13** 2022-02-21 15:02**MOT test number** 108644228623**Result** ✓ Passed**Advice** Rear Exhaust mounting defective broken off (6.1.2 (a))**Advice** Rear registration plate lamps light output poor**Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt twisted (2.1.3 (g) (i))



MOT #12

2021-02-17 13:32

MOT test number

918169130286

Result		✓ Passed
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both sides rear bush (5.3.4 (a) (i))	
Advice	Exhaust heat shield loose	
Advice	All mechanical components rusty	
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Sub-frame corroded but not seriously weakened front and rear (5.3.3 (b) (i))	
Advice	Play in steering rack inner joint(s)	
Advice	Exhaust flexi mesh worn	
Advice	Tyre slightly damaged/cracking or perishing all 4 (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Brake hose slightly deteriorated (1.1.12 (b) (ii))	

**MOT #11**

2021-02-16 09:36

MOT test number

578740623880

Result**✗ Failed**

- Advice** Exhaust flexi mesh worn
- Advice** Tyre slightly damaged/cracking or perishing all 4 (5.2.3 (d) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both sides rear bush (5.3.4 (a) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Exhaust heat shield loose
- Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** All mechanical components rusty
- Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Sub-frame corroded but not seriously weakened front and rear (5.3.3 (b) (i))
- Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #10

2019-06-08 08:12

MOT test number

518580578375

Result**✓ Passed**

- Advice** Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2018-05-28 17:09**MOT test number** 807899296909**Result** ✓ Passed**MOT #8** 2018-05-26 07:56**MOT test number** 669075569797**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #7** 2017-06-08 12:00**MOT test number** 680069402861**Result** ✓ Passed**Advice** Offside Front worn on inner edge**MOT #6** 2016-05-25 17:06**MOT test number** 652970059137**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-06-06 13:21**MOT test number** 739577055181**Result** ✓ Passed**MOT #4** 2014-06-09 13:09**MOT test number** 348000564189**Result** ✓ Passed



MOT #3 2013-06-11 15:58

MOT test number 475002663106

Result ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

MOT #2 2013-06-11 15:58

MOT test number 277282763426

Result ✗ Failed

Notice Child seat fitted not allowing full inspection of adult belt

Pass with rectification Nearside Front Headlamp not working on dipped beam (1.7.5a)

MOT #1 2012-04-27 11:17

MOT test number 398168212147

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 February 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	20 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	SC09FFX
Plate since	2019-03-29
Current registration	SC09FFX
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-19
Last registration	2024-02-16
Complete history	See info



Registration #1	2009-06-19	24 mi
Registration #2	2012-04-27	16.935 mi
Registration #3	2013-06-11	22.586 mi
Registration #4	2014-06-09	29.706 mi
Registration #5	2015-06-06	35.658 mi
Registration #6	2016-05-25	40.947 mi
Registration #7	2017-06-08	48.386 mi
Registration #8	2018-05-26	53.327 mi
Registration #9	2018-05-28	53.334 mi
Registration #10	2019-05-29	55.337 mi
Registration #11	2019-05-29	55.337 mi
Registration #12	2019-05-29	55.337 mi
Registration #13	2019-05-29	55.337 mi
Registration #14	2019-05-29	55.337 mi
Registration #15	2019-05-29	55.337 mi
Registration #16	2019-05-29	55.337 mi
Registration #17	2019-05-29	55.337 mi
Registration #18	2019-05-29	55.337 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9G49373