



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA T SPORT VVTI
Colour	Silver
Year of manufacture	2003
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	189 BHP
Max. torque	179 Nm at 6.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-21
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-11
MOT pass rate	86 %
MOT passed	18
Failed MOT tests	3
Total advice items	42
Total items failed	3

MOT #21	2023-07-12 14:46
MOT test number	339602954986
Result	✓ Passed
Next expiry date	2024-07-11

MOT #20	2022-07-12 08:40
MOT test number	472462956230
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Under body surface corrosion
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Front Headlamp lens slightly defective both sides (4.1.1 (b) (i))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))

**MOT #19** 2022-07-11 15:06**MOT test number** 951496957973**Result** ✗ Failed**Minor** Front Headlamp lens slightly defective both sides (4.1.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Under body surface corrosion**Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #18** 2021-06-19 11:05**MOT test number** 253491738286**Result** ✓ Passed**MOT #17** 2020-05-28 10:13**MOT test number** 507944158678**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #16** 2019-06-03 10:35**MOT test number** 349162732430**Result** ✓ Passed**MOT #15** 2018-05-22 09:01**MOT test number** 830314484100**Result** ✓ Passed

**MOT #14** 2017-05-22 14:17**MOT test number** 147238372652**Result** ✓ Passed**Advice** Front Body has slight corrosion chassis (6.1.B.2)**Advice** Engine cover and under tray fitted**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Rear Body has slight corrosion chassis (6.1.B.2)**MOT #13** 2016-05-28 12:19**MOT test number** 763963793955**Result** ✓ Passed**MOT #12** 2015-05-23 09:37**MOT test number** 306093645190**Result** ✓ Passed**MOT #11** 2014-06-20 11:08**MOT test number** 927981974109**Result** ✓ Passed**Advice** Power steering pipe(s) or hose(s) slightly corroded (2.3.2)**MOT #10** 2013-06-10 09:15**MOT test number** 256251163113**Result** ✓ Passed**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #9

2012-06-08 17:46

MOT test number

137290862136

Result

✓ Passed

- Advice

Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice

Offside Front Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)
- Advice

Offside Rear Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)
- Notice

Nearside front tyre is perishing
- Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Nearside Front Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)
- Advice

Nearside Rear Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)
- Advice

Parking brake lever has little reserve travel (3.1.6b)
- Notice

Offside front tyre has damage to sidewall and is perishing

**MOT #8**

2012-06-08 09:49

MOT test number

127950362177

Result**✗ Failed****Advice** Nearside Front Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)**Advice** Nearside Rear Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Offside Rear coil spring incomplete (2.4.C.1a)**Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Notice** Nearside front tyre is perishing**Advice** Offside Front Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)**Advice** Offside Rear Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Offside front tyre has damage to sidewall and is perishing**MOT #7**

2011-06-11 13:54

MOT test number

248502061178

Result**✓ Passed****MOT #6**

2011-06-11 11:07

MOT test number

605862461110

Result**✗ Failed****Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #5** 2010-06-21 14:19**MOT test number** 353032170176**Result** ✓ Passed**MOT #4** 2009-08-19 12:37**MOT test number** 911101439276**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2008-08-22 16:47**MOT test number** 510685338227**Result** ✓ Passed**Notice** N/s/r tyre worn on inner edge**MOT #2** 2007-08-24 15:02**MOT test number** 391326037406**Result** ✓ Passed**MOT #1** 2006-08-23 18:04**MOT test number** 851455536217**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
11 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	11 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YK53VTJ
Plate since	2019-03-28
Current registration	YK53VTJ
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-09-01
Last registration	2023-07-12
Complete history	See info



Registration #1	2003-09-01	29 mi
Registration #2	2006-08-23	17.496 mi
Registration #3	2007-08-24	22.401 mi
Registration #4	2008-08-22	27.022 mi
Registration #5	2009-08-19	30.821 mi
Registration #6	2010-06-21	31.729 mi
Registration #7	2011-06-11	34.992 mi
Registration #8	2011-06-11	34.992 mi
Registration #9	2012-06-08	37.659 mi
Registration #10	2012-06-08	37.659 mi
Registration #11	2013-06-10	39.854 mi
Registration #12	2014-06-20	42.006 mi
Registration #13	2015-06-20	44.157 mi
Registration #14	2015-06-20	44.157 mi
Registration #15	2015-06-20	44.157 mi
Registration #16	2015-06-20	44.157 mi
Registration #17	2015-06-20	44.157 mi
Registration #18	2015-06-20	44.157 mi
Registration #19	2015-06-20	44.157 mi
Registration #20	2015-06-20	44.157 mi
Registration #21	2015-06-20	44.157 mi
Registration #22	2015-06-20	44.157 mi
Registration #23	2015-06-20	44.157 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Max. allowed weight	1595 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	2ZZ0115893