

Ø



General information

Make	LEXUS
Model	IS 300H SPORT
Colour	White
Year of manufacture	2018
Top speed	125 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	220 BHP
Max. torque	520 Nm at 4.200 rpm
Engine capacity	2.494 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	В







Internet history

Entry 1	
Date	2021-02-01
Pictures	10
Listing price	View report









source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-15
MOT pass rate	50 %
MOT passed	4
Failed MOT tests	4
Total advice items	14
Total items failed	9

MOT #8	2024-04-16 03:42
MOT test number	988185664096
Result	✓ Passed
Next expiry date	2025-04-15

MOT #7	2024-04-04 02:25
MOT test number	683735311085
Result	🗙 Failed
Fail Offside Front Track rod end ball joint dust cover excessively damaged or deter longer prevents the ingress of dirt (2.1.3 (g) (ii))	riorated so that it no
Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Fail Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))	
Fail Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	

MOT #6	2023-08-17 15:23	
MOT test	number 979156589906	
Result	✓ Passed	
Advice	Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing and worn on outer edge (5.2.3 (d) (ii))	
Advice	Advice Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing and worn on outer edge (5.2.3 (d) (ii))	





MOT #5		2023-08-17 15:13
MOT test	number	346301178580
Result		🗙 Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing and worn on inne	r edge (5.2.3 (d) (ii))
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weake	ened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing and worn on inner o	edge (5.2.3 (d) (ii))
Advice	Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weal	kened (1.1.14 (a) (ii))
Fail B	Brake pedal has insufficient reserve travel (1.1.2 (a))	
MOT #4		2023-08-17 09:29
MOT #4 MOT test	number	436705169665

MOT test	t number	436/05169665
Result		🗙 Failed
Fail O	Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakene	d (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing and worn on inner edg	ge (5.2.3 (d) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1	1.14 (a) (ii))
Fail B	Brake pedal has insufficient reserve travel (1.1.2 (a))	
Fail N	Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice	Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing and worn on inner e	dge (5.2.3 (d) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	14 (a) (ii))

MOT #3	2022-09-05 10:51
MOT test number	750792611345
Result	✓ Passed





MOT #2	2021-09-14 14:42
MOT test number	758811799292
Result	✓ Passed
MOT #1	2021-09-14 09:43
MOT test number	691802146010
Result	🗙 Failed
Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	



Tax & MOT check

X Untaxed Tax expired: 25 March 2024	✓ MOT Expires: 15 April 2025
Tax status	Expired at 25 March 2024
Days left	35 days too late
MOT expiry date	15 April 2025
Full MOT history	See MOT history
Tax calculation	
Vehicle class	59

Vehicle class	59
Band	F
First licence fee (12 months)	£ 175,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-





Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Anne
Туре	K K
Damage 2	AMPLE
Damage 2	e et - I - I
Date	S.
Category	AMPT
Туре	

Extra LEXUS salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this LEXUS had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-09-11
Last registration	2024-04-16
Complete history	See info



Registration #1	2018-09-11	20 mi
Registration #2		11.777 esi
Registration #3	2021-09-14	62.538 mi
Registration #4	2021-09-14	62.538 mi
Registration #5	2022-09-05	71.565 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		11.777 esi
Registration #10		11.377 mi

More info >





Car features

S0225	Air conditioning
S0295	
\$0482	
\$0501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight	
Width	1810 mm
Height	1430 mm
Length	4680 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg
Additional information	
Fuel tank capacity	66 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	2AR1969611