



TOYOTA

**R559SGC**

report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA SR
Colour	Silver
Year of manufacture	1998
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	154 Nm at 4.400 rpm
Engine capacity	1.762 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-04-28
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-05-17
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	45
Total items failed	5

MOT #23 2023-05-12 11:33

MOT test number 915126316046

Result ✓ Passed

Next expiry date 2024-05-17

**Advice** Fuel filler neck corroded

**Advice** Sub-frame corroded but not seriously weakened and various suspension and brake components (5.3.3 (b) (i))

**Advice** Fuel filler cap temporary

MOT #22 2023-05-09 14:23

MOT test number 695584872550

Result ✗ Failed

**MAJOR** Front Headlamp aim too low both (4.1.2 (a))

**Advice** Sub-frame corroded but not seriously weakened and various suspension and brake components (5.3.3 (b) (i))

**Advice** Fuel filler neck corroded

**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Fuel filler cap temporary



<b>MOT #21</b>	2022-05-18 11:38
<b>MOT test number</b>	732976151609
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front cv boot worn but not excessively
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #20</b>	2022-05-04 10:42
<b>MOT test number</b>	956007297621
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>MAJOR</b>	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
<b>MAJOR</b>	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
<b>Advice</b>	Offside Front cv boot worn but not excessively
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>MAJOR</b>	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

<b>MOT #19</b>	2020-12-15 14:19
<b>MOT test number</b>	100251533590
<b>Result</b>	✓ Passed

<b>MOT #18</b>	2020-12-15 10:45
<b>MOT test number</b>	644229575604
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Offside Front Position lamp not working (4.2.1 (a) (ii))
<b>MAJOR</b>	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
<b>MAJOR</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>MAJOR</b>	Exhaust system insecure (6.1.2 (a))

**MOT #17** 2019-06-26 14:10**MOT test number** 602430162141**Result** ✓ Passed**MOT #16** 2019-06-24 15:23**MOT test number** 640144376148**Result** ✗ Failed**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MAJOR** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #15** 2018-06-05 11:00**MOT test number** 838952594485**Result** ✓ Passed**MOT #14** 2017-07-18 09:27**MOT test number** 714427995828**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #13** 2017-07-17 10:20**MOT test number** 803434088828**Result** ✗ Failed**Fail** Anti-lock braking system component missing (3.4.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #12** 2016-06-28 09:37**MOT test number** 897607566154**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11** 2015-06-15 11:38**MOT test number** 298036065175**Result** ✓ Passed**Advice** Offside coil spring corroded (2.4.C.1b)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**MOT #10** 2014-06-25 10:49**MOT test number** 256056474452**Result** ✓ Passed**MOT #9** 2013-07-09 09:24**MOT test number** 686560493184**Result** ✓ Passed**MOT #8** 2012-06-28 10:54**MOT test number** 885420682191**Result** ✓ Passed**Notice** Oil Leak

**MOT #7** 2011-07-08 12:10**MOT test number** 879409881127**Result** ✓ Passed**Notice** Discs rusty and pads not in full contact with the discs**Notice** All tyres perished**Notice** Exhaust rusty**Notice** Cv boots perished**Notice** Suspension weak**MOT #6** 2011-07-08 12:10**MOT test number** 405559281137**Result** ✗ Failed**Notice** Suspension weak**Notice** Discs rusty and pads not in full contact with the discs**Notice** All tyres perished**Pass with rectification** Front Headlamp aim too low (1.8)**Notice** Exhaust rusty**Notice** Cv boots perished**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2010-05-10 17:06**MOT test number** 183780430130**Result** ✓ Passed

**MOT #4** 2009-05-11 15:11**MOT test number** 303291939120**Result** ✓ Passed**Advice** Rear Lower Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2008-06-21 11:11**MOT test number** 354363178121**Result** ✓ Passed**MOT #2** 2007-06-23 09:45**MOT test number** 420384677171**Result** ✓ Passed**MOT #1** 2006-06-24 09:47**MOT test number** 234045676126**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
17 May 2024

<b>Tax status</b>	Valid until 1 December
-------------------	------------------------

<b>Days left</b>	217
------------------	-----

<b>MOT expiry date</b>	17 May 2024
------------------------	-------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	1998-05-21
Last registration	2023-05-12
Complete history	<a href="#">See info</a>



Registration #1	1998-05-21	14 mi
Registration #2	2006-06-24	57.788 mi
Registration #3	2007-06-23	69.970 mi
Registration #4	2008-06-21	82.471 mi
Registration #5	2009-05-11	90.897 mi
Registration #6	2010-05-10	96.448 mi
Registration #7	2011-07-08	100.001 mi
Registration #8	2012-06-28	105.402 mi
Registration #9	2013-07-09	113.151 mi
Registration #10	2014-06-25	118.387 mi
Registration #11	2015-06-15	123.289 mi
Registration #12	2016-06-28	127.783 mi
Registration #13	2017-06-28	132.277 mi
Registration #14	2018-06-28	136.771 mi
Registration #15	2019-06-28	141.265 mi
Registration #16	2020-06-28	145.759 mi
Registration #17	2021-06-28	150.253 mi
Registration #18	2022-06-28	154.747 mi
Registration #19	2023-06-28	159.241 mi
Registration #20	2024-06-28	163.735 mi
Registration #21	2025-06-28	168.229 mi
Registration #22	2026-06-28	172.723 mi
Registration #23	2027-06-28	177.217 mi
Registration #24	2028-06-28	181.711 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1750 mm
Height	1310 mm
Length	4425 mm

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	7AH082791