



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 SE SPORT S40
Colour	Grey
Year of manufacture	-
Top speed	138 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	230 Nm at 4.400 rpm
Cylinders	5
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-03
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #19	2021-11-02 16:36
MOT test number	488520293494
Result	✓ Passed
Next expiry date	2022-11-07

MOT #18	2020-10-22 15:32
MOT test number	162875298442
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2020-10-22 09:10
MOT test number	144767240434
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #16	2019-05-02 09:36
MOT test number	723279003986
Result	✓ Passed
Minor	Windscreen wiper blade defective (3.4 (b) (i))
Advice	Rear Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2018-05-08 15:34**MOT test number** 666670220139**Result** ✓ Passed**Advice** Anti-roll bar linkage has slight play in a ball joint both rear (2.4.G.2)**MOT #14** 2018-04-05 12:12**MOT test number** 497654805781**Result** ✗ Failed**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #13** 2016-11-29 11:19**MOT test number** 656747747799**Result** ✓ Passed**MOT #12** 2016-11-22 08:33**MOT test number** 493215142047**Result** ✗ Failed**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #11** 2015-11-13 15:03**MOT test number** 830097835317**Result** ✓ Passed

**MOT #10**

2014-11-17 15:25

MOT test number

356991924310

Result

✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Direction indicator has light sources not illuminating, but not more than 50%
(1.4.A.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Rear Direction indicator has light sources not illuminating, but not more than 50%
(1.4.A.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2013-11-21 10:40

MOT test number

197135423313

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #8**

2012-11-20 10:25

MOT test number

445385722358

Result

✓ Passed

MOT #7

2012-11-20 10:25

MOT test number

448645722376

Result

✗ Failed

Pass with rectification Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #6** 2012-02-14 10:23**MOT test number** 527725942018**Result** ✓ Passed**Notice** Sideskirts fitted**MOT #5** 2011-02-22 15:45**MOT test number** 107843151037**Result** ✓ Passed**Notice** Bellypan and sideskirts fitted**MOT #4** 2011-02-22 10:51**MOT test number** 188113851059**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Bellypan and sideskirts fitted**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-03-09 11:23**MOT test number** 953258460020**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-03-26 17:28**MOT test number** 152105389408**Result** ✓ Passed



MOT #1	2008-04-02 17:14
MOT test number	120883998033
Result	✓ Passed




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-03-26
Last registration	2021-11-02
Complete history	See info



Registration #1	2005-03-26	11 mi
Registration #2	2008-04-02	5.975 mi
Registration #3	2009-03-26	15.255 mi
Registration #4	2010-03-09	25.102 mi
Registration #5	2011-02-22	33.505 mi
Registration #6	2011-02-22	33.505 mi
Registration #7	2012-02-14	41.944 mi
Registration #8	2012-11-20	47.141 mi
Registration #9	2013-11-21	56.205 mi
Registration #10	2014-11-17	64.520 mi
Registration #11	2015-05-20	75.377 mi
Registration #12	2015-05-20	75.377 mi
Registration #13	2015-05-20	75.377 mi
Registration #14	2015-05-20	75.377 mi
Registration #15	2015-05-20	75.377 mi
Registration #16	2015-05-20	75.377 mi
Registration #17	2015-05-20	75.377 mi
Registration #18	2015-05-20	75.377 mi
Registration #19	2015-05-20	75.377 mi
Registration #20	2015-05-20	75.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1368 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	3821521
---------------	---------