



report date: 2024-03-29

General information

Make	KIA
Model	SPORTAGE CRDI KX-3
Colour	Black
Year of manufacture	2017
Top speed	114 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	373 Nm at 1.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date 2021-02-01

Pictures 9

Listing price [View report](#)



source: autoonline.co.uk



MOT history

MOT expiry date	2024-12-06
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	3

MOT #6	2023-11-29 15:26
MOT test number	962946073251
Result	✓ Passed
Next expiry date	2024-12-06
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush splitting (5.3.4 (a) (i))

MOT #5	2023-11-29 12:00
MOT test number	223833382743
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush splitting (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2022-12-05 09:32**MOT test number** 237620559593**Result** ✓ Passed**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated starting to split (5.3.4 (b) (i))**Advice** Offside Front Tyre slightly damaged cut/chunk missing on sidewall (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**MOT #3** 2021-12-01 15:06**MOT test number** 120347095070**Result** ✓ Passed**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2021-12-01 11:32**MOT test number** 743089598315**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #1** 2020-11-10 12:20**MOT test number** 158484130530**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
6 December 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	EJ67FGV
Plate since	2019-03-29
Current registration	EJ67FGV
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-12-07
Last registration	2023-11-29
Complete history	See info



Registration #1	2017-12-07	7 mi
Registration #2	2020-11-10	31.298 mi
Registration #3	2020-11-10	31.298 mi
Registration #4	2021-12-01	39.423 mi
Registration #5	2023-11-29	39.423 mi
Registration #6	2023-11-29	39.423 mi
Registration #7	2023-11-29	39.423 mi
Registration #8	2023-11-29	39.423 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	83%
Pedestrian	66%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1645 mm
Length	4480 mm
Wheel base	2670 mm
Kerb weight	1859 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HAHZ224644