





report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER TD ADVENTURE STATION WAGON
Colour	Red
Year of manufacture	2015
Top speed	90 mph
0 - 100 km/h	15.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 kW / 123 HP / 122 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	29.1 mpg
Consumption combined	25.5 mpg
CO2 emission	295 g/km
CO2 label	M



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-10-05

Pictures 36

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-30
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	7

MOT #9	2024-03-22 14:54
MOT test number	722675152634
Result	✓ Passed
Next expiry date	2025-03-30
Advice Outer n/s o/s foot rest corroded	

MOT #8	2023-03-21 10:40
MOT test number	331070378970
Result	✓ Passed

MOT #7	20)22-03-31 12:02
MOT test	number	532521533164
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #6 2022-03-30 14:58

MOT test number 339089379036

Result X Failed

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Advice Coolant level low

MOT #5 2021-03-01 16:13

MOT test number 192837373764

Result \(\sqrt{Passed} \)

MOT #4 2020-03-25 14:23

MOT test number 957750511303

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect Slight Leak (5.3.2 (b))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material Front to rear pipes slightly corroded both (1.1.11 (c))

MOT #3 2019-04-08 12:55

MOT test number 187614156928

Result
✓ Passed

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords Cracked Round Tread (5.2.3 (d) (i))

Advice Nearside Rear Passenger seat(s) missing at time of test

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Cracked Round Tread (5.2.3 (d) (i))

CarCheck.co.uk page 4/12



Result

Fail

ST15UAY report date: 2024-03-29

× Failed

MOT #2 2018-05-08 09:04 520833242483

MOT #1 2018-05-03 10:58

MOT test number 388623515085

Fail Offside Rear Brake pad(s) less than 1.5 mm thick Both (3.5.1g)

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick Both (3.5.1g)

Fail Offside Windscreen wiper does not clear the windscreen effectively Torn (8.2.2)

Nearside Windscreen wiper does not clear the windscreen effectively Torn (8.2.2)

Advice Front Brake pad(s) wearing thin Both Sides (3.5.1g)

CarCheck.co.uk page 5/12



ST15UAY

report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	30 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report here for the results.

Damage 1

Date
Category

Type

Damage 2
Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



ST15UAY

report date: 2024-03-29

\sim		الصد	- ! - !	torv
UV	vne	r rد	אוו	norv

For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

2000000	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



ST15UAY

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-22
Last registration	2024-03-22
Complete history	See info



Registration #1	2015-05-22	23 mi
Registration #2	2018-05-03	23.325 mi
Registration #3	2018-05-08	23.393 mi
Registration #4	2019-04-08	29.936 mi
Registration #5	2020-03-25	36.046 mi
Registration #6	2021-03-01	47.050 mi
Registration #7		11.777 mi
Registration #8		0.074
Registration #9		11.777 mi
Registration #10		0.074
Registration #11		10.777 es

More info >

CarCheck.co.uk page 11/12



		_		
- 11	manciai	חר ג.	MOIG	nt.
	mensioı	אט כוו	welu	III.

Width	1992 mm
Height	2181 mm
Length	4785 mm
Wheel base	2794 mm
Kerb weight	2125 kg
Max. allowed weight	3050 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	7
Number of axles	2
Engine number	150909061246DT224

CarCheck.co.uk page 12/12