



General information

Make	MINI
Model	MINI (R60) COOPER S ALL4
Colour	Grey
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-08-15
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #11	2023-08-16 15:23
MOT test number	121948347043
Result	✓ Passed
Next expiry date	2024-08-15
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10	2023-08-16 09:54
MOT test number	278117840222
Result	✗ Failed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Front Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #9	2022-07-14 12:39
MOT test number	858938731196
Result	✓ Passed
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2021-01-29 15:57
MOT test number	729942047156
Result	✓ Passed

**MOT #7** 2020-03-23 11:13**MOT test number** 932124353732**Result** ✓ Passed**MOT #6** 2019-03-28 11:08**MOT test number** 200688775667**Result** ✓ Passed**MOT #5** 2018-04-06 16:43**MOT test number** 522184340610**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2017-03-16 13:13**MOT test number** 644390583057**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**Advice** Oil leak**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2016-03-15 13:11**MOT test number** 354401539831**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #2	2015-04-02 17:49
MOT test number	128742795021
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2014-03-28 13:43
MOT test number	296247884088
Result	✓ Passed
Notice	Enging oil leak (oil control valve leaking)
Notice	Under-trays fitted obscuring some underside components
Notice	Near side front alloy buckled
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-03-26
Last registration	2023-08-16
Complete history	See info



Registration #1	2011-03-26	17 mi
Registration #2	2014-03-28	13.016 mi
Registration #3	2015-04-02	17.571 mi
Registration #4	2016-03-15	21.868 mi
Registration #5	2017-03-16	24.859 mi
Registration #6	2018-04-06	27.468 mi
Registration #7	2019-03-28	32.689 mi
Registration #8	2020-03-29	35.277 mi
Registration #9	2021-03-29	35.277 mi
Registration #10	2022-03-29	35.277 mi
Registration #11	2023-03-29	35.277 mi
Registration #12	2024-03-29	35.277 mi
Registration #13	2025-03-29	35.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Kerb weight	1405 kg
Max. allowed weight	1865 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

A0111914