




report date: 2025-02-13

General information

Make	FIAT
Model	MAREA ELX
Colour	Black
Year of manufacture	1998
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	154 Nm at 4.400 rpm
Engine capacity	1.747 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg





Internet history

Entry 3

Date	2021-09-11
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2


Date	2021-09-10
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-09
Pictures	47
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-06-22
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	50
Total items failed	15

MOT #24	2022-06-23 12:14
MOT test number	822628303325
Result	✓ Passed
Next expiry date	2023-06-22

MOT #23	2022-06-17 06:29
MOT test number	837222954411
Result	✗ Failed

MAJOR Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))

MAJOR Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength floor (5.3.6 (a) (i))

MAJOR Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength floor (5.3.6 (a) (i))



MOT #22 2021-05-18 08:13

MOT test number 399620266612

Result ✔ Passed

- Advice** Nearside Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Outer sill (6.2.2 (d) (i))
- Advice** Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security whole under body (6.2.2 (d) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Obligatory mirror slightly damaged outer case (3.3 (b) (i))
- Advice** Offside Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Outer sill (6.2.2 (d) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #21 2020-06-02 07:01

MOT test number 525844523501

Result ✔ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #20 2020-05-27 08:43

MOT test number 442302938339

Result ✘ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Outer sill (6.2.2 (d) (i))

MOT #19 2019-05-15 08:23

MOT test number 880020471796

Result ✔ Passed

- Advice** Offside Front tyre cracking between treads
- Advice** Minor corrosion to underside+outer sills
- Advice** Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))



MOT #18 2018-06-15 10:29

MOT test number 639066819857

Result ✔ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

Advice Corrosion to under side + both outer sills

MOT #17 2018-06-06 11:32

MOT test number 889829413053

Result ✘ Failed

Advice Corrosion to under side + both outer sills

MAJOR Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Nearside Front Brake pipe excessively corroded (1.1.11 (c))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

MOT #16 2017-05-31 08:50

MOT test number 597248142422

Result ✔ Passed

Advice Drivers door handle stiff

Advice Slight corrosion on both sills

Advice Tyres cracking between treads



MOT #15 2016-05-17 11:28

MOT test number 757178895148

Result ✔ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Rear coil spring corroded both sides (2.4.C.1b)
- Advice** Rear Direction indicator slightly discoloured both sides (1.4.A.2f)
- Advice** Brake pipe slightly corroded both front to rears rear sections (3.6.B.2c)
- Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

MOT #14 2015-05-19 09:28

MOT test number 707009635111

Result ✔ Passed

- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #13 2014-05-19 11:02

MOT test number 558429734126

Result ✔ Passed

- Notice** Corrosion on floor panels



MOT #12	2013-05-23 15:19
MOT test number	295973543414
Result	✓ Passed
Advice	Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
Advice	Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #11	2012-05-22 11:25
MOT test number	968163942127
Result	✓ Passed

MOT #10	2012-05-17 13:47
MOT test number	745288032100
Result	✗ Failed
Fail	Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
Notice	Rear coil springs corroded
Fail	Offside Front Obligatory mirror seriously deteriorated, affecting the rear view (8.1.2a)
Fail	Nearside Seat belt anchorage prescribed area is excessively corroded (5.2.6)
Notice	Complete underneath of vehicle light corrosion

MOT #9	2011-06-15 10:28
MOT test number	137586161172
Result	✓ Passed



MOT #8 2011-05-11 13:33

MOT test number 178841731114

Result ✗ Failed

- Fail** Offside Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Nearside Rear Sub-frame has excessive play in a pin/bush (2.4.G.2)
- Fail** Nearside Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Rear Sub-frame has excessive play in a pin/bush (2.4.G.2)

MOT #7 2010-05-10 15:41

MOT test number 131610930143

Result ✓ Passed

- Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)

MOT #6 2010-05-05 16:40

MOT test number 924275120161

Result ✗ Failed

- Fail** Nearside Front Tie bar/rod has excessive play in a ball joint (2.4.G.2)
- Fail** Offside rear brake binding (3.7.B.1)
- Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)
- Fail** Offside rear brake recording little or no effort (3.7.B.5a)

MOT #5 2009-05-05 13:53

MOT test number 964545829118

Result ✓ Passed

- Advice** Nearside Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Offside Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)



MOT #4 2009-05-01 09:17

MOT test number 144441729176

Result ✗ Failed

Fail Service brake: efficiency below requirements (3.7.B.7)

Advice Offside Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Offside Brake pipe excessively corroded (3.6.B.2c)

Advice Nearside Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Fail Nearside Brake pipe excessively corroded (3.6.B.2c)

MOT #3 2008-05-20 09:09

MOT test number 414171648145

Result ✓ Passed

MOT #2 2007-05-08 11:29

MOT test number 400518327163

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2006-05-31 08:38

MOT test number 990331556162

Result ✓ Passed



Tax & MOT check

×
Untaxed
Tax expired:
31 March 2023

×
MOT
Expired:
22 June 2023

Tax status Expired at 31 March 2023

Days left 717 days too late

MOT expiry date 22 June 2023

Full MOT history [See MOT history](#)




Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	YX11
Plate since	2015-05-29
Current registration	YX11
Plate since	2015-05-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	1998-06-09
Last registration	2022-06-23
Complete history	See info



Registration #1	1998-06-09	27 mi
Registration #2	2006-05-31	26.567 mi
Registration #3	2007-05-08	27.920 mi
Registration #4	2008-05-20	30.019 mi
Registration #5	2009-05-01	31.536 mi
Registration #6	2009-05-05	31.538 mi
Registration #7	2010-05-05	33.317 mi
Registration #8	2010-05-10	33.335 mi
Registration #9	2011-05-11	35.603 mi
Registration #10	2011-06-15	35.742 mi
Registration #11	2012-05-17	37.392 mi
Registration #12	2012-05-22	37.398 mi
Registration #13	2013-05-23	39.013 mi
Registration #14	2014-05-19	40.082 mi
Registration #15	2015-05-20	41.797 mi
Registration #16	2016-05-20	43.512 mi
Registration #17	2017-05-20	45.227 mi
Registration #18	2018-05-20	46.942 mi
Registration #19	2019-05-20	48.657 mi
Registration #20	2020-05-20	50.372 mi
Registration #21	2021-05-20	52.087 mi
Registration #22	2022-05-20	53.802 mi
Registration #23	2023-05-20	55.517 mi
Registration #24	2024-05-20	57.232 mi
Registration #25	2025-05-20	58.947 mi
Registration #26	2026-05-20	60.662 mi

Registration #27

2025-05-20

20 2025-05-20

Registration #28

2025-05-20

20 2025-05-20

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★ ★ ★ ★ ★

Video [see crash video](#)



Dimensions & weight

Width	1741 mm
Height	1425 mm
Length	4390 mm
Wheel base	2540 mm
Kerb weight	1195 kg

Additional information

Fuel tank capacity	63 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	1042488