





report date: 2024-03-28

### General information

Make	BMW	
Model	640 640D M SPORT GRAN COUPE	
Colour	Grey	
Year of manufacture	2018	
Top speed	155 mph	
Gearbox	8 speed automatic	

# Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	49.6 mpg
CO2 emission	152 g/km
CO2 label	G



CarCheck.co.uk page 1/11




Internet history

Entry 1

Date 2022-03-08

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-03-22
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	5
Total items failed	0

MOT #5	2024-03-14 14:02
MOT test number	479154362782
Result	✓ Passed
Next expiry date	2025-03-22
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2023-03-23 15:38
MOT test number	147881352656
Result	<b>✓</b> Passed
MOT #3	2022-03-12 18:14
MOT test number	212028544707
Result	<b>✓</b> Passed
MOT #2	2021-05-19 14:33
MOT test number	387222274434
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



MOT #1 2021-05-19 09:56

**MOT test number** 276476393797

Result	<b>×</b> Faile
<b>DANGEROUS</b> (d) (ii))	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3
DANGEROUS (d) (ii))	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3
<b>DANGEROUS</b> (d) (ii))	Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3
<b>DANGEROUS</b> (d) (ii))	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	22 March 2025
Full MOT history	See MOT history

### Tax calculation

-	
Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



YW18KAA

report date: 2024-03-28

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



YW18KAA

report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

YW18KAA

report date: 2024-03-28

# For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a>.

More info >

## Plate changes

See in this check if this BMW had different number plates.

More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



YW18KAA

report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-06-25
Last registration	2024-03-14
Complete history	See info



Registration #1	2018-06-25	7 mi
Registration #2	2021-05-19	29.736 mi
Registration #3	2021-05-19	29.736 mi
Registration #4		77,777 66
Registration #5		11.777 es
Registration #6		71,777 66
Registration #7		11,177 mi

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1894 mm
Height	1392 mm
Length	5007 mm
Wheel base	2968 mm
Kerb weight	1810 kg
Max. allowed weight	2410 kg

# Additional information

		•
Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

**Engine number** 58199972