



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	B-CLASS B170 SE
Colour	Blue
Year of manufacture	2006
Top speed	114 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	155 Nm at 4.000 rpm
Engine capacity	1.699 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-09-22
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	30
Total items failed	10

MOT #20	2023-09-20 10:12
MOT test number	245094291422
Result	✓ Passed
Next expiry date	2024-09-22
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #19	2023-09-19 07:49
MOT test number	609074100845
Result	✗ Failed
MAJOR	Brake performance unable to be tested o /s/f caliper insecure (1.2.1 (g))
DANGEROUS	Offside Front Hydraulic brake calliper insecurely mounted and braking performance affected (1.1.16 (c) (ii))
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #18	2022-08-24 10:54
MOT test number	982645102603
Result	✓ Passed
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2021-09-07 14:41**MOT test number** 825444217274**Result** ✓ Passed**MOT #16** 2020-09-22 16:41**MOT test number** 392912718086**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material both side (1.1.11 (c))**MOT #15** 2019-09-23 15:19**MOT test number** 642694426663**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases Middle exhaust joint slight blow (6.1.2 (a))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Both rear fuel tank filler pipes are heavily corroded**Advice** Nearside Front Brake pipe corroded, covered in grease or other material To rear corroded (1.1.11 (c))**MOT #14** 2018-09-03 15:29**MOT test number** 688305059891**Result** ✓ Passed**Advice** Undertrays fitted**Advice** Offside Brake pipe corroded, covered in grease or other material main (1.1.11 (c))**Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #13** 2018-09-03 15:29**MOT test number** 636233063202**Result** ✗ Failed**Advice** Offside Brake pipe corroded, covered in grease or other material main (1.1.11 (c))**Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Undertrays fitted**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #12** 2017-09-14 08:31**MOT test number** 653055034308**Result** ✓ Passed**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Brake pipe slightly corroded main (3.6.B.2c)**Advice** Nearside Brake pipe slightly corroded main (3.6.B.2c)**Advice** Undertrays fitted**MOT #11** 2016-08-31 13:17**MOT test number** 412078659484**Result** ✓ Passed**Advice** Undertrays fitted

**MOT #10** 2016-08-31 08:00**MOT test number** 882411774057**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Undertrays fitted**MOT #9** 2015-09-09 12:30**MOT test number** 226324309713**Result** ✓ Passed**MOT #8** 2015-09-09 08:14**MOT test number** 104038469146**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid o/s (8.2.3)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** N/s/f tyre worn on outside**Fail** Windscreen washer provides insufficient washer liquid n/s (8.2.3)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**MOT #7** 2014-09-02 15:02**MOT test number** 449305144231**Result** ✓ Passed**MOT #6** 2013-09-17 09:36**MOT test number** 117910663268**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #5** 2013-09-17 09:36**MOT test number** 328190163269**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #4** 2012-08-23 11:17**MOT test number** 775026132241**Result** ✓ Passed**MOT #3** 2011-09-21 10:02**MOT test number** 979254461278**Result** ✓ Passed**MOT #2** 2010-08-31 10:33**MOT test number** 671953240292**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-09-02 12:23**MOT test number** 303435049227**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
22 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	22 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 YK56WLX
Plate since	2019-06-29
Current registration	 YK56WLX
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-22
Last registration	2023-09-20
Complete history	See info



Registration #1	2006-09-22	7 mi
Registration #2	2009-09-02	31.715 mi
Registration #3	2010-08-31	40.728 mi
Registration #4	2011-09-21	51.194 mi
Registration #5	2012-08-23	57.661 mi
Registration #6	2013-09-17	66.325 mi
Registration #7	2014-09-02	72.665 mi
Registration #8	2015-09-09	76.949 mi
Registration #9	2015-09-09	76.949 mi
Registration #10	2016-08-31	81.595 mi
Registration #11	2016-08-31	81.595 mi
Registration #12	2016-08-31	81.595 mi
Registration #13	2016-08-31	81.595 mi
Registration #14	2016-08-31	81.595 mi
Registration #15	2016-08-31	81.595 mi
Registration #16	2016-08-31	81.595 mi
Registration #17	2016-08-31	81.595 mi
Registration #18	2016-08-31	81.595 mi
Registration #19	2016-08-31	81.595 mi
Registration #20	2016-08-31	81.595 mi
Registration #21	2016-08-31	81.595 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1310 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26694030124500