

Ford



### General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	Silver
Year of manufacture	2014
Top speed	120 mph
0 - 100 km/h	10.9 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history	
Entry 1	
Date	2021-01-30
Pictures	1
Listing price	View report



source: autoonline.co.uk



## MOT history

MOT expiry date	2025-04-14
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	24
Total items failed	9

МОТ #20	2024-04-13 10:44
MOT test number	945364727478
Result	🗸 Passed
Next expiry date	2025-04-14
Advice Rear Tyre worn close to legal limit/worn on edge Both sides. (5.2.3 (e))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice Under-trays fitted obscuring some underside components.	

MOT #19	2024-04-13 10:44	
MOT test number	257532376059	
Result	× Failed	
Minor Windscreen damaged but not adversely affecting drive	er's view (3.2 (a) (i))	
Advice Under-trays fitted obscuring some underside components.		
Pass with rectification         Windscreen washer provides insufficient	cient washer liquid (3.5 (a))	
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Advice Rear Tyre worn close to legal limit/worn on edge Both sides. (5.2.3 (e))		





MOT #18		2023-04-15 17:15
MOT test	number	626416825950
Result		✓ Passed
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sou	rces (4.7.1 (b) (i))
Advice Front Tyre worn close to legal limit/worn on edge Both sides. (5.2.3 (e))		
Minor	Minor Front Outer Drive shaft joint constant velocity boot severely deteriorated Both sides. (6.1.7 (g) (i))	
Advice	Under-Trays fitted obscuring some underside components.	

MOT #17	2023-04-15 12:47	
MOT test number	421655322770	
Result	🗙 Failed	
Advice Under-Trays fitted obscuring some underside components.		
Fail Rear Anti-roll bar linkage ball joint excessively worn Both sides. (5.3.4 (a) (i))		
Minor Front Outer Drive shaft joint constant velocity boot severely deteriorated Both sides. (6.1.7 (g) (i))		
Advice Front Tyre worn close to legal limit/worn on edge Both sides. (5.2.3 (e))		
Fail         Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))		
Minor Registration plate lamp inoperative in the case of multiple lamps or light source	es (4.7.1 (b) (i))	

MOT #16		2022-04-11 13:14
MOT test	number	790996721442
Result		✓ Passed
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	





MOT #15	2022-04-11 12:19
MOT test number	292360065012
Result	🗙 Failed
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
<b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #14	2021-04-13 14:41
MOT test number	389652960118
Result	✓ Passed
MOT #13	2021-03-02 13:41
MOT test number	563821062993
Result	✓ Passed
MOT #12	2019-12-16 13:58
MOT test number	458884719615
Result	✓ Passed
MOT #11	2019-06-06 10:59
MOT test number	975745184745
Result	✓ Passed





MOT #10	2019-04-03 16:27
MOT test number	389944690310
Result	Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #9	2018-10-06 13:18
MOT test number	597997192310
Result	✓ Passed

MOT #8	2018-04-06 15:53
MOT test number	140432366463
Result	✓ Passed

MOT #7	2018-04-06 10:26
MOT test number	476548393898
Result	🗙 Failed
<ul> <li>Fail Nearside Front Front constant velocity joint gaiter damaged to the extent that it not the ingress of dirt etc (2.5.C.1a)</li> <li>Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</li> <li>Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)</li> </ul>	o longer prevents
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #6	2017-10-09 15:22
MOT test number	944786175225
Result	✓ Passed





MOT #5		2017-04-10 16:24
MOT test number		121729428729
Result		✓ Passed
МОТ #4		2017-02-27 15:25
MOT test number		576182708394
Result		✓ Passed
МОТ #3		2015-11-02 17:10
MOT test number		986163849620
Result		✓ Passed
MOT #2		2015-11-02 17:10
MOT test number		752690034439
Result		🗙 Failed
Pass with rectification	Stop lamp not working bothside (1.2.1b)	
MOT #1		2015-05-05 11:57
MOT test number		877815725118

MOT test number		
Result		

🗸 Passed



Tax & MOT check

X Untaxed Tax expired: 30 September 2023	✓ MOT Expires: 14 April 2025
Tax status	Expired at 30 September
Days left	212 days too late
MOT expiry date	14 April 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2014-05-16
Last registration	2024-04-13
Complete history	See info



Registration #1	2014-05-16	15 mi
Registration #2	2015-05-05	13.330 mi
Registration #3	2015-11-02	32.644 mi
Registration #4	2015-11-02	32.644 mi
Registration #5	2017-02-27	51.442 mi
Registration #6	2017-04-10	51.573 mi
Registration #7	2017-10-09	63.546 mi
Registration #8	2018-04-06	75.380 mi
Registration #9	2018-04-06	75.380 mi
Registration #10	2018-10-06	87.240 mi
Registration #11	2019-04-03	101.778 mi
Registration #12		11.777 esi
Registration #13		11.777 est
Registration #14		11.777 esi
Registration #15		11.777 est
Registration #16		11.777 esi
Registration #17		11.777 est
Registration #18		11.777 esi
Registration #19		11.777 est
Registration #20		10.100 aug
5		
Registration #21		11.777 esi





### Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Number of axles	2
Engine number	ET47075