



PEUGEOT

FE05BJV

report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 SPORT
Colour	Silver
Year of manufacture	-
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	94 Nm at 2.700 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-13
Pictures	6
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #21	2022-06-07 06:23
MOT test number	177137447096
Result	✓ Passed
Next expiry date	2023-07-06
Advice	Fuel tank strap corroded

MOT #20	2021-07-02 15:37
MOT test number	343058993970
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19	2020-07-07 08:15
MOT test number	842550611275
Result	✓ Passed

MOT #18	2020-07-06 13:13
MOT test number	650505407543
Result	✗ Failed
MAJOR	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
MAJOR	Offside Front Brake pipe excessively corroded (1.1.11 (c))

**MOT #17**

2020-06-22 10:03

MOT test number

815655365871

Result

✗ Failed

Advice Brake pipe corroded, covered in grease or other material All metal (1.1.11 (c))**MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MAJOR** Nearside Brake master cylinder/servo mounting prescribed area is excessively corroded Bulkhead (1.1.21 (e) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #16**

2018-10-15 13:37

MOT test number

359014731704

Result

✓ Passed

Advice Both front wiper blades split**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated Both (5.3.4 (b) (i))**Minor** Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Both front (2.1.3 (g) (i))**Advice** Brake master cylinder/servo mounting prescribed area is corroded but not considered excessive (1.1.21 (e) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #15**

2017-10-18 11:17

MOT test number

694514671142

Result

✓ Passed

Advice Nearside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Slight noise from wheel bearing

Advice Brake master cylinder/servo mounting prescribed area is corroded but not considered excessive (3.6.C.3)

**MOT #14** 2016-10-10 14:22**MOT test number** 703902910719**Result** ✓ Passed**MOT #13** 2016-10-10 09:45**MOT test number** 712873652463**Result** ✗ Failed**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #12** 2015-10-15 09:22**MOT test number** 491585360391**Result** ✓ Passed**MOT #11** 2014-10-22 12:43**MOT test number** 867555394260**Result** ✓ Passed**Notice** Front brake pads getting low**Notice** Osf tyre sidewall badly split**MOT #10** 2014-10-21 15:15**MOT test number** 359114394467**Result** ✗ Failed**Fail** Offside Front Braking system leaking (3.6.A.1)**Fail** Centre Rear Rear fog lamp not working (1.3.2b)**Notice** Front brake pads getting low**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Osf tyre sidewall badly split



MOT #9	2013-10-17 16:45
MOT test number	415160793291
Result	✓ Passed
Notice	Front brake discs corroded inside edge

MOT #8	2013-10-16 15:55
MOT test number	339099083251
Result	✗ Failed
Fail	Nearside Front Brake hose ferrule excessively corroded (3.6.B.4e)
Notice	Front brake discs corroded inside edge
Fail	Centre Exhaust system not adequately supported (7.1.1)
Fail	Rear Exhaust system not adequately supported (7.1.1)
Fail	Offside Front Brake hose ferrule excessively corroded (3.6.B.4e)
Notice	Nsf tyre very low on pressure
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Rear Exhaust has a major leak of exhaust gases (7.1.2)

MOT #7	2012-10-12 14:20
MOT test number	319736382486
Result	✓ Passed
Notice	Nsf tyre 2mm
Notice	Exhaust back box heavily corroded

**MOT #6** 2012-10-11 15:32**MOT test number** 376335082478**Result** ✗ Failed**Fail** Nearside Rear rear brake binding (3.7.B.1)**Notice** Nsf tyre 2mm**Notice** Exhaust back box heavily corroded**Fail** Offside Rear rear brake binding (3.7.B.1)**Notice** Air con leak at condensor /pipes**MOT #5** 2011-10-25 14:00**MOT test number** 499878091256**Result** ✓ Passed**Notice** Radiator showing signs of weeping coolant**Notice** Exhaust backbox outer skin poor**Notice** Slight play in o/s/f inner rack joint**MOT #4** 2011-05-19 15:50**MOT test number** 416369631117**Result** ✓ Passed**MOT #3** 2010-05-22 10:18**MOT test number** 662082840132**Result** ✓ Passed**Notice** Slight damage n/s, underside of vehicle**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)



MOT #2	2009-05-13 15:46
MOT test number	414473039131
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Radiator corroded
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #1	2008-05-15 10:46
MOT test number	661306638175
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	FE05BJV
Plate since	2019-03-29
Current registration	FE05BJV
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-05-18
Last registration	2022-06-07
Complete history	See info



Registration #1	2005-05-18	13 mi
Registration #2	2008-05-15	21.182 mi
Registration #3	2009-05-13	32.177 mi
Registration #4	2010-05-22	39.483 mi
Registration #5	2011-05-19	42.336 mi
Registration #6	2011-10-25	46.752 mi
Registration #7	2012-10-11	49.100 mi
Registration #8	2012-10-12	49.107 mi
Registration #9	2013-10-16	50.704 mi
Registration #10	2013-10-17	50.704 mi
Registration #11	2014-10-21	51.260 mi
Registration #12	2014-10-22	51.260 mi
Registration #13	2015-05-20	51.260 mi
Registration #14	2015-05-20	51.260 mi
Registration #15	2015-05-20	51.260 mi
Registration #16	2015-05-20	51.260 mi
Registration #17	2015-05-20	51.260 mi
Registration #18	2015-05-20	51.260 mi
Registration #19	2015-05-20	51.260 mi
Registration #20	2015-05-20	51.260 mi
Registration #21	2015-05-20	51.260 mi
Registration #22	2015-05-20	51.260 mi
Registration #23	2015-05-20	51.260 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	985 kg
Max. allowed weight	1405 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FP7N4673360