



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Silver
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg



LABEL UNKNOWN



Internet history

Entry 2


Date	2021-07-27
Pictures	6
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-27
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #5	2021-08-11 09:53
MOT test number	822727294212
Result	✓ Passed
Next expiry date	2022-08-10

MOT #4	2020-10-15 15:14
MOT test number	300961431872
Result	✓ Passed

- Advice** No exhaust emission print out due to diesel low emission
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement started to crack (5.3.4 (a) (i))
- Advice** Under cover tray fitted obscuring some components

MOT #3	2019-04-25 09:02
MOT test number	611865310362
Result	✓ Passed

- Advice** Rear Brake pad(s) wearing thin appear low (1.1.13 (a) (ii))
- Advice** Vehicle fitted with under body trays obscuring underside from inspection
- Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #2	2018-04-20 15:39
MOT test number	883999232881
Result	✓ Passed
Advice	Nearside Front tyre cracking
Advice	Tyre pressure monitoring light indicates a tyre is low in pressure
Advice	Nearside washer jet inop but the o/s still emits enough water to clean the screen at time of test
Advice	Vehicles internal headlight adjuster altered to recheck lights

MOT #1	2018-04-20 08:45
MOT test number	198027146198
Result	✗ Failed
Fail	Parking brake lever has no reserve travel (3.1.6b)
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Nearside Front tyre cracking
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Rear brake recording little or no effort (3.7.B.5a)
Advice	Tyre pressure monitoring light indicates a tyre is low in pressure
Advice	Nearside washer jet inop but the o/s still emits enough water to clean the screen at time of test



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2015-04-27
Last registration	2021-08-11
Complete history	See info



Registration #1	2015-04-27	22 mi
Registration #2	2018-04-20	41.704 mi
Registration #3	2018-04-20	41.704 mi
Registration #4	2019-04-25	55.896 mi
Registration #5	2020-05-20	55.896 mi
Registration #6	2020-05-20	55.896 mi
Registration #7	2020-05-20	55.896 mi
Registration #8	2021-08-11	55.896 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDFZ359220