



report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2013
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-04-11
Pictures	9
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2023-10-06
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	16
Total items failed	1

MOT #11	2022-10-07 13:17
MOT test number	923084101484
Result	✓ Passed
Next expiry date	2023-10-06
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2022-10-04 09:11
MOT test number	360548811299
Result	✗ Failed
MAJOR	Offside Front Upper Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2022-01-05 18:00
MOT test number	370762536843
Result	✓ Passed
Advice	Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8	2020-11-23 18:06
MOT test number	720292305516
Result	✓ Passed

**MOT #7** 2019-10-19 14:04**MOT test number** 484089972436**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Exhaust has a minor leak of exhaust gases turbo (6.1.2 (a))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2019-10-19 12:54**MOT test number** 136230928721**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases turbo (6.1.2 (a))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**DANGEROUS** Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #5** 2018-10-06 14:42**MOT test number** 223372995006**Result** ✓ Passed**MOT #4** 2018-10-06 09:13**MOT test number** 213257421416**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Hydraulic brake calliper insecurely mounted bolt missing (1.1.16 (c) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Hang brake high



MOT #3	2017-10-19 12:50
MOT test number	561702457135
Result	✓ Passed

MOT #2	2017-10-19 12:50
MOT test number	866388468111
Result	✗ Failed
<div>Pass with rectification</div> Offside Rear Stop lamp not working (1.2.1b)	

MOT #1	2016-11-07 09:55
MOT test number	875334352545
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 July 2023

X

MOT

Expired:  
6 October 2023

Tax status	Expired at 1 July 2023
Days left	303 days too late
MOT expiry date	6 October 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-11-26
Last registration	2022-10-07
Complete history	<a href="#">See info</a>



Registration #1	2013-11-26	18 mi
Registration #2	2016-11-07	64.512 mi
Registration #3	2017-10-19	79.663 mi
Registration #4	2017-10-19	79.663 mi
Registration #5	2018-10-06	87.066 mi
Registration #6	2018-10-06	87.066 mi
Registration #7	2019-10-19	100.357 mi
Registration #8	2019-10-19	100.357 mi
Registration #9	2019-10-19	100.357 mi
Registration #10	2019-10-19	100.357 mi
Registration #11	2019-10-19	100.357 mi
Registration #12	2019-10-19	100.357 mi
Registration #13	2019-10-19	100.357 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	4945767