



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC TDCI
Colour	Black
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg
CO2 emission	187 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-08-29
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	25
Total items failed	9

MOT #16	2023-09-22 07:45
MOT test number	246210356034
Result	✓ Passed
Next expiry date	2024-09-21
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Nearside Indicator tell-tale inoperative (4.9.1 (a) (i))

MOT #15	2023-09-22 07:45
MOT test number	946878853538
Result	✗ Failed
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor	Nearside Indicator tell-tale inoperative (4.9.1 (a) (i))

**MOT #14**

2023-07-28 07:53

MOT test number

718877463023

Result**✗ Failed****Advice** Rear Exhaust mounting defective (6.1.2 (a))**Fail** Offside Front Tyre has ply or cords exposed 215/55r16 (5.2.3 (d) (ii))**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Indicator tell-tale inoperative (4.9.1 (a) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #13**

2022-07-26 13:52

MOT test number

165361311779

Result**✓ Passed**

**MOT #12**

2022-07-25 12:46

MOT test number

359612328962

Result

✗ Failed

- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Fail** Emission control equipment obviously defective dpf pressure hose melted and broken (8.2.2.1 (a))
- Advice** Rear exhaust heat shield is loose
- Advice** Rear Exhaust mounting defective broken off (6.1.2 (a))
- Fail** Offside Rear Suspension arm pin or bush excessively worn trailing arm front pivot bush (5.3.4 (a) (i))
- Fail** Nearside Position lamp not working (4.2.1 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Front Exhaust has a minor leak of exhaust gases flexi has a hole in it on the side (6.1.2 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn trailing arm front pivot bush (5.3.4 (a) (i))

MOT #11

2021-07-27 12:13

MOT test number

925327264529

Result

✓ Passed

MOT #10

2020-09-22 07:32

MOT test number

196442210388

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

2019-08-22 08:02

MOT test number

226016359703

Result

✓ Passed

**MOT #8** 2018-08-29 09:26**MOT test number** 214870462000**Result** ✓ Passed**MOT #7** 2017-08-05 08:31**MOT test number** 478289994497**Result** ✓ Passed**MOT #6** 2016-07-30 09:48**MOT test number** 310851467430**Result** ✓ Passed**Advice** Front brake disc worn**MOT #5** 2015-08-10 15:18**MOT test number** 459792025218**Result** ✓ Passed**MOT #4** 2014-12-23 10:39**MOT test number** 965817954389**Result** ✓ Passed**Notice** Rear tyres worn on inner edges**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-12-18 12:59**MOT test number** 297892053344**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2013-12-18 12:59
MOT test number	579992053348
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)

MOT #1	2012-11-30 14:00
MOT test number	706845732309
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	ND59UXW
Plate since	2019-03-29
Current registration	ND59UXW
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-29
Last registration	2023-09-22
Complete history	See info



Registration #1	2009-12-29	7 mi
Registration #2	2012-11-30	44.548 mi
Registration #3	2013-12-18	72.454 mi
Registration #4	2014-12-23	95.589 mi
Registration #5	2015-08-10	98.683 mi
Registration #6	2016-07-30	126.609 mi
Registration #7	2017-08-05	135.386 mi
Registration #8	2018-08-29	141.606 mi
Registration #9	2019-08-22	146.404 mi
Registration #10	2020-08-22	151.202 mi
Registration #11	2021-08-22	156.000 mi
Registration #12	2022-08-22	160.798 mi
Registration #13	2023-08-22	165.596 mi
Registration #14	2024-08-22	170.394 mi
Registration #15	2025-08-22	175.192 mi
Registration #16	2026-08-22	179.990 mi
Registration #17	2027-08-22	184.788 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2850 mm
Kerb weight	1580 kg
Max. allowed weight	2190 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	9B00180
---------------	---------