





General information

Make	VOLVO
Model	V60 D4 INSCRIPTION
Colour	Silver
Year of manufacture	2016
Top speed	140 mph
0 - 60 mph	7.9 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	400 Nm at 2.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С





AO16LOF report date: 2024-03-28

Internet history

Entry 2	
Date	2021-07-21
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 1	
Date	2021-07-14
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-02
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	17
Total items failed	4

MOT #6	2023-06-27 10:42
MOT test number	393585279854
Result	✓ Passed
Next expiry date	2024-07-02

MOT #5		2022-06-17 14:17
MOT test	number	359923895504
Result		Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #4	2022-06-17 09:18
MOT test number	858132055645
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification Offside Headlamp aim too high (4.1.2 (a))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2021-07-01 14:43
MOT test number	736030492994
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge 235/40/18 (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge 235/40/18 (5.2.3 (e))	
Advice Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 235/40/18 (5.2.3 (e))
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or lig (b) (i))	ght sources (4.7.1
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 235/40/18 (5.2.3 (e))



MOT #2		2020-07-03 09:43
MOT test	number	281350647877
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #1	2	019-03-13 13:01
MOT test r	number	763111037357
Result		✓ Passed
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a)	(i))

AO16LOF report date: 2024-03-28



Tax & MOT check

✓ Taxed Tax due: 1 August 2024	MOT Expires: 2 July 2024
Tax status	Valid until 1 August
Days left	94
MOT expiry date	2 July 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	
Damage 2	AMPLE
Danlage 2	E CAT ON
Date	1. E
Category	 AMP
Туре	

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-23
Last registration	2023-06-27
Complete history	See info



Registration #1	2016-03-23	13 mi
Registration #2	2019-03-13	47.512 mi
Registration #3	2020-07-03	64.193 mi
Registration #4	2021-07-01	79.630 mi
Registration #5		11.777 esi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight	
Width	2019 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1680 kg
Max. allowed weight	2270 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/12