





report date: 2024-03-29

General information

Make	AUDI
Model	A2 TDI
Colour	Black
Year of manufacture	2001
Top speed	107 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	195 Nm at 2.200 rpm
Engine capacity	1.390 сс
Cylinders	3
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	78.5 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/16



Internet history

Entry 2

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-12-23
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/16



MOT history

MOT expiry date	2022-05-30
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	51
Total items failed	25

MOT #22		2021-05-06 15:02
MOT test	number	145644431512
Result		✓ Passed
Next expi	ry date	2022-05-30
Advice	Driver's door catch deteriorated but the door can still be readily opened and	closed (6.2.3 (c) (i))
Advice	Nearside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #21	2020-05-22 08:57
MOT test number	147534077446
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #20	2019-05-16 14:24
MOT test number	420288097927
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/16



report date: 2024-03-29

MOT test number

Result

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #18 2018-05-29 16:37 **MOT** test number 627730134858 Result ✓ Passed **Advice** Nearside headlamp bracket broken but headlamp still secure **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front linkage dust cover slightly damaged Advice Oil leak, but not excessive (8.4.1 (a) (i)) **Minor** Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #17 2018-05-29 14:49 **MOT** test number 255698568501 Result × Failed **Advice** Nearside headlamp bracket broken but headlamp still secure **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Minor Front Windscreen wiper blade defective (3.4 (b) (i)) **Advice** Offside Front linkage dust cover slightly damaged Fail Nearside Front Electrical wiring heavily deteriorated pad sensor (4.11 (b) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))

CarCheck.co.uk page 4/16



report date: 2024-03-29

MOT test number

149071120023


Result

Advice Oil leak

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)

Advice Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)



CarCheck.co.uk page 5/16



report date: 2024-03-29

MOT test number

665536557226

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt both sides (2.4.G.2)

Advice Oil leak

MOT #13 2016-05-31 12:56 **MOT test number** 618044288106 Result × Failed **Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i) Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Advice Oil leak **Advice** Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt both sides (2.4.G.2)Pass with rectification Rear Registration plate lamp not working (1.1.C.1d)

MOT #12	2015-05-12 14:03
MOT test	number 456762835121
Result	✓ Passed
Advice (2.4.G.2)	Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/16



report date: 2024-03-29

MOT #11 2013-11-30 14:36

MOT test number 577424333392

Result ✓ Passed

Advice Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #10 2013-11-30 14:36

MOT test number 736294333361

Result X Failed

Advice Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #9 2013-11-29 16:12

MOT test number 305453333306

Result X Failed

Fail Fuel system component leaking (7.2.3)

Fail Nearside Stop lamp not working (1.2.1b)

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Front Windscreen wiper blade insecure (8.2.2)

Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

CarCheck.co.uk page 7/16



report date: 2024-03-29

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Oil leak

Advice Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2012-09-28 16:57 **MOT** test number 566892272250 × Failed Result **Pass with rectification** Nearside Rear Body has a sharp edge caused by damage (6.1.C.1) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Advice Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2) Notice Oil leak Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6	2011-06-02 14:50
MOT test number	376613151193
Result	✓ Passed

CarCheck.co.uk page 8/16



Fail

Y138YVA

report date: 2024-03-29

MOT #5 2011-05-26 17:35 **MOT** test number 376336441102 Result **X** Failed Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b) Fail Nearside Front Headlamp aim too high and too far to the right. (1.8) **Advice** Offside Front Shock absorber has a light misting of oil (2.7.3) Nearside Rear Direction indicators incorrect colour (1.4.A.2f) Fail Offside Front Brake hose excessively deteriorated (3.6.B.4d) Fail Fail Offside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a) **Notice** Nearside front inner c/v gaitor split **Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3) Fail Nearside Front Direction indicators incorrect colour (1.4.A.2f) **Advice** Outer Front Exhaust has part of the system slightly deteriorated (7.1.1a) Fail Offside Rear Direction indicators incorrect colour (1.4.A.2f)

MOT #4		2010-05-18 16:16
MOT test number		592098630165
Result		✓ Passed
MOT #3		2010-05-18 16:16
MOT test number		800978030188
Result		X Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)	

Anti-lock braking system warning lamp does not illuminate (3.4.1b)

CarCheck.co.uk page 9/16



MOT #2	2009-05-20 16:59
MOT test number	740400549102
Result	✓ Passed
MOT #1	2007-05-18 17:00
MOT #1 MOT test number	2007-05-18 17:00 354278837186

CarCheck.co.uk page 10/16



Tax & MOT check



MOT

Expired:
30 May 2022

Tax expired: 1 January 2023

Tax status

Expired at 1 January 2023

Days left 484 days too late

MOT expiry date 30 May 2022

Full MOT history See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 11/16



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/16



Owner history

*		
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report J		ve?

	More info	>
Plate changes See in this check if this AUDI had different number plates.		
· ·		
Number of plates		,
Current registration	UK NEZ	
Plate since		
Current registration	UK Min	
Plate since		
	More info	>

CarCheck.co.uk page 13/16



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2001-03-10
Last registration	2021-05-06
Complete history	See info



2001-03-10	27 mi
2007-05-18	87.672 mi
2009-05-20	99.414 mi
2010-05-18	103.584 mi
2011-05-26	108.061 mi
2011-06-02	108.129 mi
2012-09-28	115.568 mi
2013-11-29	120.460 mi
2013-11-30	120.460 mi
2015-05-12	122.963 mi
2016-05-31	124.129 mi
	11.777 es
	77.777 au
	2007-05-18 2009-05-20 2010-05-18 2011-05-26 2011-06-02 2012-09-28 2013-11-29 2013-11-30 2015-05-12 2016-05-31

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Dimensions & weight

Width	1890 mm
Height	1553 mm
Length	3826 mm
Wheel base	2405 mm
Kerb weight	990 kg

Additional information

Fuel tank capacity	34 I
Fuel delivery	Direct Injection
Number of doors	5
Engine number	AMF 091975

CarCheck.co.uk page 16/16