



General information

Make	FIAT
Model	GRAND PUNTO ACTIVE
Colour	Grey
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-09
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-27
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	45
Total items failed	16

MOT #21	2024-03-28 10:21
MOT test number	409460568309
Result	✓ Passed
Next expiry date	2025-03-27
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Coil spring corroded all 4 coil springs rusty (5.3.1 (b) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20	2024-03-08 12:05
MOT test number	131746638269
Result	✗ Failed
Fail	Front Headlamp reflector seriously defective not working as should (4.1.1 (b) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both front discs (1.1.14 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Front Anti-roll bar ball joint likely to become detached drop link (5.3.4 (a) (ii))
Advice	Coil spring corroded all 4 springs corroded (5.3.1 (b) (i))

**MOT #19** 2023-02-17 09:04**MOT test number** 801719753782**Result** ✓ Passed

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. 16% (1.4.2 (a) (i))

MOT #18 2023-02-13 10:52**MOT test number** 764797471257**Result** ✗ Failed

- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Position lamp switch does not operate in accordance with the requirements (4.2.2 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Position lamp switch does not operate in accordance with the requirements (4.2.2 (a))

MOT #17 2022-02-14 11:03**MOT test number** 893926574173**Result** ✓ Passed

Advice Exhaust has a minor leak of exhaust gases front flexi (6.1.2 (a))

MOT #16 2022-02-08 11:06**MOT test number** 802675517827**Result** ✗ Failed

- Fail** Offside Front Sub-frame corroded to the extent that the rigidity of the assembly is significantly reduced marked in yellow (6.1.1 (c) (i))
- Fail** Nearside Front Sub-frame corroded to the extent that the rigidity of the assembly is significantly reduced marked in yellow (6.1.1 (c) (i))

**MOT #15**

2021-02-12 16:15

MOT test number

767876197743

Result

✓ Passed

Advice Offside Rear shock absorber slightly corroded**Advice** Nearside Rear shock absorber slightly corroded**MOT #14**

2020-02-11 17:37

MOT test number

340248219405

Result

✓ Passed

Advice Front Brake pipe corroded, covered in grease or other material to offside rear (1.1.11 (c))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear shock absorber slightly corroded**Advice** Front Brake pipe corroded, covered in grease or other material to nearside rear (1.1.11 (c))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear shock absorber slightly corroded**MOT #13**

2020-02-11 17:37

MOT test number

327391687932

Result

✗ Failed

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear shock absorber slightly corroded**Advice** Front Brake pipe corroded, covered in grease or other material to offside rear (1.1.11 (c))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Front Brake pipe corroded, covered in grease or other material to nearside rear (1.1.11 (c))**Advice** Offside Rear shock absorber slightly corroded**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12**

2019-02-18 17:46

MOT test number

202151150872

Result

✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Coolant leak radiator
- Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))
- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))

MOT #11

2019-02-18 17:46

MOT test number

944945927009

Result

✗ Failed

- Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Coolant leak radiator
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #10** 2018-02-14 16:08**MOT test number** 193823568421**Result** ✓ Passed**MOT #9** 2017-08-16 08:08**MOT test number** 324060069327**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2016-08-09 09:44**MOT test number** 712339406645**Result** ✓ Passed**MOT #7** 2015-08-20 08:05**MOT test number** 899907185222**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-08-11 10:00**MOT test number** 329193324415**Result** ✓ Passed**MOT #5** 2013-08-02 11:53**MOT test number** 619614813209**Result** ✓ Passed**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #4** 2013-08-02 11:53**MOT test number** 117594413285**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high and too far to the right. (1.8)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #3** 2012-08-13 11:06**MOT test number** 139886122268**Result** ✓ Passed**MOT #2** 2011-08-08 09:32**MOT test number** 936370921262**Result** ✓ Passed**MOT #1** 2011-08-08 09:32**MOT test number** 505560921223**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
27 March 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	27 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-07-25
Last registration	2024-03-28
Complete history	See info



Registration #1	2008-07-25	17 mi
Registration #2	2011-08-08	21.191 mi
Registration #3	2012-08-13	26.630 mi
Registration #4	2013-08-02	31.117 mi
Registration #5	2014-08-11	37.611 mi
Registration #6	2015-08-20	42.328 mi
Registration #7	2016-08-09	46.312 mi
Registration #8	2017-08-16	51.247 mi
Registration #9	2018-02-14	52.623 mi
Registration #10	2019-02-18	56.052 mi
Registration #11	2019-02-18	56.052 mi
Registration #12	2020-03-28	56.052 mi
Registration #13	2020-03-28	56.052 mi
Registration #14	2020-03-28	56.052 mi
Registration #15	2020-03-28	56.052 mi
Registration #16	2020-03-28	56.052 mi
Registration #17	2020-03-28	56.052 mi
Registration #18	2020-03-28	56.052 mi
Registration #19	2020-03-28	56.052 mi
Registration #20	2020-03-28	56.052 mi
Registration #21	2020-03-28	56.052 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4363732