



report date: 2024-03-28

General information

Make	VOLVO
Model	V90 D4 R-DESIGN
Colour	Silver
Year of manufacture	2018
Top speed	140 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-24
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2025-03-22
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #5 2024-03-04 12:22**MOT test number** 214251076400**Result** Passed**Next expiry date** 2025-03-22

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4 2023-03-17 09:42**MOT test number** 557206929452**Result** Passed**MOT #3** 2022-03-08 14:57**MOT test number** 530649564493**Result** Passed

**MOT #2** 2021-03-23 14:58**MOT test number** 564816999270**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin both sides appear low (1.1.13 (a) (ii))
- Advice** Offside Front Nail in tyre
- Advice** Front Brake pad(s) wearing thin both sides appear low (1.1.13 (a) (ii))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt

MOT #1 2021-03-23 14:18**MOT test number** 572672943924**Result** ✗ Failed

- Fail** Nearside Rear Tyre has ply or cords exposed 245/45/18 (5.2.3 (d) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 245/45/18 (5.2.3 (d) (i))
- Advice** Rear Brake pad(s) wearing thin both sides appear low (1.1.13 (a) (ii))
- Advice** Offside Front Nail in tyre
- Advice** Front Brake pad(s) wearing thin both sides appear low (1.1.13 (a) (ii))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
22 March 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	22 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YR18FYJ
Plate since	2019-03-28
Current registration	YR18FYJ
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-22
Last registration	2024-03-04
Complete history	See info



Registration #1	2018-03-22	24 mi
Registration #2	2021-03-23	36.813 mi
Registration #3	2021-03-23	36.813 mi
Registration #4	2024-03-04	36.813 mi
Registration #5	2024-03-04	36.813 mi
Registration #6	2024-03-04	36.813 mi
Registration #7	2024-03-04	36.813 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	1895 mm
Height	1475 mm
Length	4936 mm
Wheel base	2941 mm
Kerb weight	1696 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2534144