



X966NNW

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	LUPO E
Colour	Black
Year of manufacture	2001
Top speed	94 mph
0 - 60 mph	18.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	50 BHP
Max. torque	86 Nm at 3.000 rpm
Engine capacity	999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-14
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2021-10-07
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	31
Total items failed	30

MOT #21	2020-10-06 10:58
MOT test number	289820286683
Result	✓ Passed
Next expiry date	2021-10-07

MOT #20	2019-10-08 17:12
MOT test number	145902437081
Result	✓ Passed

MOT #19	2019-10-08 17:12
MOT test number	750093742988
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))

**MOT #18**

2018-10-01 08:22

**MOT test number**

903078898071

**Result**

✓ Passed

- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2018-09-25 10:13

**MOT test number**

722089661885

**Result**

✗ Failed

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a))

**MOT #16**

2017-08-07 15:57

**MOT test number**

470083200606

**Result**

✓ Passed



MOT #15	2016-07-22 15:23
MOT test number	105125866198
Result	✓ Passed



MOT #14	2016-07-05 11:15
MOT test number	179025713748
Result	✗ Failed
Fail	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
Fail	Front Anti-roll bar missing (2.4.G.1)
Fail	Offside Side repeater not working (1.4.A.2c)
Fail	Offside Rear Coil spring not correctly located (2.4.C.2)
Fail	Battery insecure (1.9.1)
Fail	Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
Fail	Offside Front Shock absorber has a serious fluid leak (2.7.3)
Fail	Electrical wiring insecure (1.9.2a)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Front Exhaust system not adequately supported (7.1.1)
Fail	Power steering inoperative (2.3.3a)
Fail	Nearside Side repeater not working (1.4.A.2c)
Fail	Nearside Rear Coil spring not correctly located (2.4.C.2)
Fail	Offside Front position lamp(s) not working side (1.1.A.3b)
Fail	Offside Rear Tyre fouling a part of the vehicle wheel arches (4.1.D.2)
Fail	Offside Front brake caliper leaking (3.6.A.1)
Fail	Driver's airbag obviously defective (5.4.1)
Fail	Front Exhaust has a major leak of exhaust gases (7.1.2)
Fail	Electrical wiring inadequately supported (1.9.2a)

**MOT #13**

2015-06-18 16:38

**MOT test number**

477299765118

**Result**

✓ Passed

**Advice** Nearside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Offside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**MOT #12**

2015-06-15 09:24

**MOT test number**

178206465162

**Result**

✗ Failed

**Advice** Nearside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Fail** Electrical wiring insecure (1.9.2a)**Fail** Offside Headlamp aim beam image kick up to the offside (1.8)**Fail** Nearside Front passenger door cannot be opened from inside the vehicle (6.2.B.1b)**Advice** Offside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Fail** Electrical wiring insecure (1.9.2a)**Fail** Nearside Headlamp aim beam image kick up to the offside (1.8)**MOT #11**

2014-06-16 15:09

**MOT test number**

725177464102

**Result**

✓ Passed

**MOT #10**

2013-07-04 16:26

**MOT test number**

859785383116

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Nail in nearside rear tyre

**MOT #9** 2013-07-04 09:30**MOT test number** 579555383189**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Notice** Nail in nearside rear tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear rear brake binding (3.7.B.1)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #8** 2012-06-27 14:11**MOT test number** 117499472196**Result** ✓ Passed**MOT #7** 2011-07-15 12:06**MOT test number** 909036591123**Result** ✓ Passed**MOT #6** 2010-06-18 09:14**MOT test number** 213059160106**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2009-07-03 14:30**MOT test number** 343494589155**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



**MOT #4** 2008-02-19 16:43**MOT test number** 794990558024**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2007-01-05 11:03**MOT test number** 160355907022**Result** ✓ Passed**Notice** Oil leak**MOT #2** 2007-01-05 11:03**MOT test number** 232465707073**Result** ✗ Failed**Notice** Oil leak**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #1** 2006-01-05 12:36**MOT test number** 152485706022**Result** ✓ Passed



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	X966NN
Plate since	2024-03-29
Current registration	X966NN
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2001-01-05
Last registration	2020-10-06
Complete history	<a href="#">See info</a>



Registration #1	2001-01-05	12 mi
Registration #2	2006-01-05	25.564 mi
Registration #3	2007-01-05	30.815 mi
Registration #4	2008-02-19	35.762 mi
Registration #5	2009-07-03	41.412 mi
Registration #6	2010-06-18	45.041 mi
Registration #7	2011-07-15	49.061 mi
Registration #8	2012-06-27	53.202 mi
Registration #9	2013-07-04	56.209 mi
Registration #10	2013-07-04	56.221 mi
Registration #11	2014-06-16	58.315 mi
Registration #12	2015-06-16	60.315 mi
Registration #13	2016-06-16	62.315 mi
Registration #14	2017-06-16	64.315 mi
Registration #15	2018-06-16	66.315 mi
Registration #16	2019-06-16	68.315 mi
Registration #17	2020-06-16	70.315 mi
Registration #18	2021-06-16	72.315 mi
Registration #19	2022-06-16	74.315 mi
Registration #20	2023-06-16	76.315 mi
Registration #21	2024-06-16	78.315 mi
Registration #22	2025-06-16	80.315 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	925 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	AUC073028