



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Grey
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-13
Pictures	14
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #10</b>	2021-12-29 10:55
<b>MOT test number</b>	799564353652
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-12-28
<b>Advice</b>	Offside Rear shock leaking slightly
<b>Advice</b>	Offside Rear lamp damaged
<b>Advice</b>	Offside Front Inner cv boot leaking
<b>Advice</b>	Nearside Front Inner rack joint slight play
<b>Advice</b>	Coolant level low
<b>Advice</b>	Both front tyres bald inner edges

<b>MOT #9</b>	2021-12-24 10:51
<b>MOT test number</b>	903910343442
<b>Result</b>	✗ Failed
<b>Fail</b>	Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
<b>Advice</b>	Nearside Front Inner rack joint slight play
<b>Fail</b>	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
<b>Advice</b>	Coolant level low
<b>Advice</b>	Both front tyres bald inner edges
<b>Fail</b>	Stop lamp(s) light intensity significantly reduced brake light in rear window (4.3.3 (a) (ii))
<b>Advice</b>	Offside Rear shock leaking slightly
<b>Advice</b>	Offside Rear lamp damaged
<b>Advice</b>	Offside Front Inner cv boot leaking

**MOT #8** 2020-12-16 12:36**MOT test number** 180091756760**Result** ✓ Passed

- Advice** Front tyres worn on edges
- Advice** Front suspension arm bushes have slight flex
- Advice** Off side rear lamp lense has a hole repaired with tape.

**MOT #7** 2019-11-08 11:58**MOT test number** 704360159023**Result** ✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2019-11-08 11:58**MOT test number** 513007286446**Result** ✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Offside Position lamp showing white light to the rear (4.2.3 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #5** 2018-11-09 16:00**MOT test number** 799180637626**Result** ✓ Passed

**MOT #4** 2017-05-30 08:06**MOT test number** 238067836108**Result** ✓ Passed**Advice** N/s mirror indicator lens cracked**Advice** All tyres close to limits**Advice** Rear brake pads getting down**Advice** O/s/r light lens cracked**MOT #3** 2016-06-01 14:26**MOT test number** 690014241010**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2016-05-31 11:36**MOT test number** 248598336172**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #1** 2015-06-01 13:09**MOT test number** 936212555167**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>RV12OZC</b>
Plate since	2024-03-29
Current registration	<b>RV12OZC</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-05-30
Last registration	2021-12-29
Complete history	<a href="#">See info</a>



Registration #1	2012-05-30	12 mi
Registration #2	2015-06-01	106.389 mi
Registration #3	2016-05-31	135.810 mi
Registration #4	2016-06-01	135.811 mi
Registration #5	2017-05-30	156.378 mi
Registration #6	2018-11-09	173.261 mi
Registration #7	2019-05-29	191.277 mi
Registration #8	2019-05-29	191.277 mi
Registration #9	2019-05-29	191.277 mi
Registration #10	2019-05-29	191.277 mi
Registration #11	2019-05-29	191.277 mi
Registration #12	2019-05-29	191.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2041867