



report date: 2024-03-28

General information

| | |
|---------------------|-----------------|
| Make | VOLVO |
| Model | V50 E4 D SE V50 |
| Colour | Silver |
| Year of manufacture | - |
| Top speed | 130 mph |
| 0 - 60 mph | 9.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 136 BHP |
| Max. torque | 320 Nm at 2.000 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 49.6 mpg |




LABEL UNKNOWN



Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-02-15 |
| Pictures | 14 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-29 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)

**MOT history**

| | |
|-------------------------|------------------|
| MOT #19 | 2022-02-15 11:57 |
| MOT test number | 981037634553 |
| Result | ✓ Passed |
| Next expiry date | 2023-02-14 |

| | |
|------------------------|------------------|
| MOT #18 | 2021-01-04 10:16 |
| MOT test number | 837001463899 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #17 | 2020-01-03 11:34 |
| MOT test number | 789342331332 |
| Result | ✓ Passed |

Advice Child Seat fitted not allowing full inspection of adult belt

| | |
|------------------------|------------------|
| MOT #16 | 2019-01-08 15:43 |
| MOT test number | 502764381176 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #15 | 2018-02-15 09:56 |
| MOT test number | 889887644286 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #14 | 2017-01-27 12:20 |
| MOT test number | 778207867570 |
| Result | ✓ Passed |

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #13** 2017-01-20 09:47**MOT test number** 412605251583**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #12** 2016-01-30 11:08**MOT test number** 541678965300**Result** ✓ Passed**MOT #11** 2016-01-28 10:08**MOT test number** 122858628376**Result** ✗ Failed**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure Inner edge (4.1.D.1b)**Advice** O/S/F tyre wearing on inner edge**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #10** 2015-03-23 16:39**MOT test number** 798232485093**Result** ✓ Passed**Notice** Nearside headlamp slightly discoloured

**MOT #9** 2015-03-23 10:06**MOT test number** 188742285429**Result** ✗ Failed**Notice** Nearside headlamp slightly discoloured**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #8** 2014-03-19 08:41**MOT test number** 928798574056**Result** ✓ Passed**Notice** Nearside front tyre has damage to outer wall**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-04-04 10:29**MOT test number** 796374693084**Result** ✓ Passed**MOT #6** 2013-04-04 10:29**MOT test number** 637744393088**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #5** 2012-04-04 15:45**MOT test number** 787225192030**Result** ✓ Passed

**MOT #4** 2012-04-03 10:30**MOT test number** 756474992050**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Obligatory mirror missing (8.1.1)**MOT #3** 2011-04-08 10:23**MOT test number** 856508891075**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-04-08 10:12**MOT test number** 272338890079**Result** ✓ Passed**MOT #1** 2009-04-09 12:20**MOT test number** 842179099061**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-09-28 |
| Current registration | ***** |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2006-04-13 |
| Last registration | 2022-02-15 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-04-13 | 22 mi |
| Registration #2 | 2009-04-09 | 28.278 mi |
| Registration #3 | 2010-04-08 | 37.761 mi |
| Registration #4 | 2011-04-08 | 46.358 mi |
| Registration #5 | 2012-04-03 | 54.454 mi |
| Registration #6 | 2012-04-04 | 54.457 mi |
| Registration #7 | 2013-04-04 | 61.299 mi |
| Registration #8 | 2014-03-19 | 69.650 mi |
| Registration #9 | 2015-03-23 | 77.099 mi |
| Registration #10 | 2015-03-23 | 77.100 mi |
| Registration #11 | 2016-01-28 | 82.232 mi |
| Registration #12 | 2016-01-28 | 82.232 mi |
| Registration #13 | 2016-01-28 | 82.232 mi |
| Registration #14 | 2016-01-28 | 82.232 mi |
| Registration #15 | 2016-01-28 | 82.232 mi |
| Registration #16 | 2016-01-28 | 82.232 mi |
| Registration #17 | 2016-01-28 | 82.232 mi |
| Registration #18 | 2016-01-28 | 82.232 mi |
| Registration #19 | 2016-01-28 | 82.232 mi |
| Registration #20 | 2016-01-28 | 82.232 mi |
| Registration #21 | 2016-01-28 | 82.232 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1452 mm |
| Length | 4514 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1489 kg |
| Max. allowed weight | 1960 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 52 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|---------|
| Number of axles | 2 |
| Engine number | 4014833 |