



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 S
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	136 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-25
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT #17	2022-06-22 15:56
MOT test number	630302318699
Result	✓ Passed
Next expiry date	2023-06-21
Advice	Front Inner Anti-roll bar ball joint has slight play both (5.3.4 (a) (i))

MOT #16	2022-06-22 10:43
MOT test number	557293011119
Result	✗ Failed
MAJOR	Offside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Front Inner Anti-roll bar ball joint has slight play both (5.3.4 (a) (i))
MAJOR	Front Anti-roll bar ball joint excessively worn both (5.3.4 (a) (i))
MAJOR	Emissions NOx sensor obviously defective (8.2.1.1 (a))

MOT #15	2021-03-30 15:37
MOT test number	339272220110
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))

MOT #14	2021-03-30 13:27
MOT test number	931061248071
Result	✗ Failed
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
DANGEROUS	Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
MAJOR	Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))
Advice	Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))
MAJOR	Front Anti-roll bar linkage ball joint excessively worn BOTH (5.3.4 (a) (i))

**MOT #13** 2020-03-25 09:47**MOT test number** 671416863277**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12** 2019-04-26 12:05**MOT test number** 883080081048**Result** ✓ Passed**Advice** Front discs worn/deteriated**Advice** Rear exhaust join has slight blow**Advice** Tyre worn close to legal limit/worn on edge n/s/r tyre wearing uneven (flat areas ) close to limit - inner 3/4 (5.2.3 (e))**MOT #11** 2019-04-23 11:46**MOT test number** 875699676702**Result** ✗ Failed**MAJOR** Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt o/s/f outer cv boot split/leaking (6.1.7 (g) (ii))**Advice** Front discs worn/deteriated**Advice** Tyre worn close to legal limit/worn on edge n/s/r tyre wearing uneven (flat areas ) close to limit - inner 3/4 (5.2.3 (e))**Advice** Rear exhaust join has slight blow**MOT #10** 2018-04-27 09:42**MOT test number** 924983463608**Result** ✓ Passed**Advice** Front discs slightly deteriated/worn

**MOT #9** 2018-04-23 11:49**MOT test number** 465654942498**Result** ✗ Failed**Fail** Registration plate lamp not working n/s/r (1.1.C.1d)**Fail** Drive shaft which forms part of the suspension coupling gaiter damaged to the extent that it no longer prevents the ingress of dirt etc o/s/f outer cv boot split/leaking (2.4.G.4e)**Fail** Stop lamp not working n/s/r (1.2.1b)**Advice** Front discs slightly deteriorated/worn**Fail** Windscreen washer provides insufficient washer liquid front no motor sound (8.2.3)**Fail** Exhaust system not adequately supported front mount broken off (7.1.1)**MOT #8** 2017-04-25 10:15**MOT test number** 527973892169**Result** ✓ Passed**MOT #7** 2017-04-25 10:15**MOT test number** 582938241549**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #6** 2016-04-25 10:07**MOT test number** 369994748351**Result** ✓ Passed**MOT #5** 2016-03-17 12:10**MOT test number** 162402978906**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened Front (3.5.1i)

**MOT #4** 2016-03-17 12:10**MOT test number** 766185977800**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Tyre tread depth below requirements of 1.6mm Both rear (4.1.E.1)**Advice** Brake disc worn, pitted or scored, but not seriously weakened Front (3.5.1i)**MOT #3** 2015-03-25 08:26**MOT test number** 437304185063**Result** ✓ Passed**MOT #2** 2014-04-10 16:41**MOT test number** 285870704430**Result** ✓ Passed**MOT #1** 2013-01-30 12:14**MOT test number** 927230433012**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KY59YYD
Plate since	2019-09-28
Current registration	KY59YYD
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-16
Last registration	2022-06-22
Complete history	<a href="#">See info</a>



Registration #1	2009-09-16	25 mi
Registration #2	2013-01-30	17.172 mi
Registration #3	2014-04-10	30.256 mi
Registration #4	2015-03-25	40.717 mi
Registration #5	2016-03-17	50.977 mi
Registration #6	2016-03-17	50.977 mi
Registration #7	2016-04-25	51.394 mi
Registration #8	2017-04-25	60.711 mi
Registration #9	2017-04-25	60.711 mi
Registration #10	2018-04-23	76.427 mi
Registration #11	2019-05-22	91.377 mi
Registration #12	2019-05-22	91.377 mi
Registration #13	2019-05-22	91.377 mi
Registration #14	2019-05-22	91.377 mi
Registration #15	2019-05-22	91.377 mi
Registration #16	2019-05-22	91.377 mi
Registration #17	2019-05-22	91.377 mi
Registration #18	2019-05-22	91.377 mi
Registration #19	2019-05-22	91.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1748 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1245 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Engine number**

FGAJ0529384