



L6MGL

report date: 2024-03-28

General information

Make	VOLVO
Model	V70 V70 T5 SE
Colour	Green
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	225 Nm at 4.500 rpm
Cylinders	5
Fuel type	Petrol
Consumption city	20.3 mpg
Consumption extra urban	37.2 mpg
Consumption combined	28.5 mpg



**MOT history**

<b>MOT #18</b>	2020-03-17 10:36
<b>MOT test number</b>	410210853695
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-03-30
<b>Advice</b>	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

<b>MOT #17</b>	2019-03-29 10:45
<b>MOT test number</b>	375244795633
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
<b>Minor</b>	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

<b>MOT #16</b>	2018-03-09 15:04
<b>MOT test number</b>	226625914715
<b>Result</b>	✓ Passed
<b>Advice</b>	Play in steering rack inner joint(s)

**MOT #15**

2018-03-08 08:33

**MOT test number**

112937305014

**Result****✗ Failed**

- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Rear tyres wearing on edges and sidewalls perished
- Fail** Registration plate lamp not working x 2 (1.1.C.1d)
- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Fail** Offside Tyre has a cut in excess of the requirements deep enough to reach the ply or cords and nearside front side walls (4.1.D.1a)
- Advice** Play in steering rack inner joint(s)
- Fail** Nearside Rear Upper Rear position lamp(s) not working (1.1.A.3b)
- Fail** Offside Direction indicator incorrect colour and nearside rear (1.4.A.2f)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)

**MOT #14**

2017-03-21 11:24

**MOT test number**

999795867539

**Result****✓ Passed****MOT #13**

2016-03-31 11:07

**MOT test number**

503985217150

**Result****✓ Passed****MOT #12**

2015-03-20 12:22

**MOT test number**

579769175046

**Result****✓ Passed**

**MOT #11** 2014-03-14 12:51**MOT test number** 906863674016**Result** ✓ Passed**MOT #10** 2013-03-05 12:52**MOT test number** 388954163090**Result** ✓ Passed**MOT #9** 2012-03-13 13:01**MOT test number** 997923772014**Result** ✓ Passed**MOT #8** 2011-03-24 10:50**MOT test number** 725623581098**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Fuel cap sealing washer starting to perish but still seals**Advice** Offside Inner Ball joint has slight play (2.2.B.1f)**MOT #7** 2010-03-26 13:51**MOT test number** 324025280084**Result** ✓ Passed**Notice** Slight play in offside front rack end

**MOT #6** 2010-03-25 16:33**MOT test number** 241574080072**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.5c)**Notice** Slight play in offside front rack end**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #5** 2009-03-11 12:55**MOT test number** 570740179059**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2008-03-06 14:28**MOT test number** 710486768076**Result** ✓ Passed**MOT #3** 2008-03-06 11:02**MOT test number** 994926968053**Result** ✗ Failed**Fail** Exhaust system not adequately supported (7.1.1)**Fail** Offside Headlamp excessively damaged so that the light output is severely reduced (1.7.5a)**MOT #2** 2007-03-26 13:07**MOT test number** 364825487025**Result** ✓ Passed



MOT #1	2006-02-13 16:38
MOT test number	761994546034
Result	✓ Passed
Advice	Offside Inner Track rod end ball joint has slight play (2.2.B.1f)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2002-11-21
Last registration	2020-03-17
Complete history	<a href="#">See info</a>



Registration #1	2002-11-21	25 mi
Registration #2	2006-02-13	36.551 mi
Registration #3	2007-03-26	41.733 mi
Registration #4	2008-03-06	50.914 mi
Registration #5	2008-03-06	50.914 mi
Registration #6	2009-03-11	59.906 mi
Registration #7	2010-03-25	68.615 mi
Registration #8	2010-03-26	68.617 mi
Registration #9	2011-03-24	76.259 mi
Registration #10	2012-03-13	84.186 mi
Registration #11	2013-03-20	92.117 mi
Registration #12	2014-03-20	100.048 mi
Registration #13	2015-03-20	107.979 mi
Registration #14	2016-03-20	115.910 mi
Registration #15	2017-03-20	123.841 mi
Registration #16	2018-03-20	131.772 mi
Registration #17	2019-03-20	139.703 mi
Registration #18	2020-03-17	147.634 mi
Registration #19	2021-03-17	155.565 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1804 mm
Height	1465 mm
Length	4710 mm
Wheel base	2755 mm
Kerb weight	1525 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	2975565