



RENAULT



SY6IVGP


report date: 2024-03-29

General information

Make	RENAULT
Model	MODUS GRAND DYNAMIQUE VVT
Colour	Beige
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.5 seconds
0 - 60 mph	12.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	82 kW / 112 HP / 110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 2

Date	2024-03-15
Pictures	50
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-12
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	24
Total items failed	17

MOT #16	2024-03-13 14:49
MOT test number	410932753022
Result	✓ Passed
Next expiry date	2025-03-12

MOT #15	2024-03-11 15:28
MOT test number	756821047682
Result	✗ Failed

- Fail

Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail

Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail

Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail

Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))
- Fail

Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail

Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail

Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail

Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #14**

2023-03-21 12:29

MOT test number

575642394582

Result

✓ Passed

- Advice** The front and rear brake imbalance is close to the maximum allowed
- Advice** The front radiator support frame is excessively corroded
- Advice** The front and rear brake discs and pads are corroded
- Advice** The colour of both rear indicator bulbs is deteriorated
- Advice** The front to rear metal brake pipes are covered in grease not allowing inspection

MOT #13

2022-04-19 15:47

MOT test number

411641365733

Result

✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material All round in grease (1.1.11 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12

2021-03-29 14:59

MOT test number

232727715370

Result

✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Items removed from driver's view prior to test

**MOT #11**

2020-09-01 15:23

MOT test number

837080342458

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))**Advice** Front Sub-frame is corroded but structural rigidity is not significantly reduced Underside sub frame (6.1.1 (c) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10**

2020-08-28 14:13

MOT test number

229685469436

Result

✗ Failed

Advice Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Sub-frame is corroded but structural rigidity is not significantly reduced Underside sub frame (6.1.1 (c) (i))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #9**

2019-05-21 09:35

MOT test number

520213230710

Result

✓ Passed

Advice Nearside Front Suspension component ball joint has slight play (5.3.4 (a) (i))**MOT #8**

2018-05-22 14:46

MOT test number

316845269778

Result

✓ Passed

**MOT #7** 2018-05-22 09:31**MOT test number** 246888288725**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2017-05-26 11:22**MOT test number** 903230574524**Result** ✓ Passed**MOT #5** 2017-05-26 10:09**MOT test number** 924697202889**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #4** 2016-04-13 10:47**MOT test number** 283668283651**Result** ✓ Passed**MOT #3** 2016-04-11 09:59**MOT test number** 678802587342**Result** ✗ Failed**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**Fail** Front front brake application uneven (3.7.B.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Rear rear brake binding (3.7.B.1)**MOT #2** 2015-04-20 08:09**MOT test number** 749800615161**Result** ✓ Passed



MOT #1	2014-07-17 12:24
MOT test number	166018194165
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
12 March 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	12 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-10-12
Last registration	2024-03-13
Complete history	See info



Registration #1	2011-10-12	6 mi
Registration #2	2014-07-17	20.292 mi
Registration #3	2015-04-20	23.069 mi
Registration #4	2016-04-11	27.375 mi
Registration #5	2016-04-13	27.378 mi
Registration #6	2017-05-26	30.976 mi
Registration #7	2017-05-26	30.976 mi
Registration #8	2018-05-22	34.093 mi
Registration #9	2018-05-22	34.096 mi
Registration #10	2019-05-21	37.470 mi
Registration #11	2019-05-21	37.470 mi
Registration #12	2019-05-21	37.470 mi
Registration #13	2019-05-21	37.470 mi
Registration #14	2019-05-21	37.470 mi
Registration #15	2019-05-21	37.470 mi
Registration #16	2019-05-21	37.470 mi
Registration #17	2019-05-21	37.470 mi
Registration #18	2019-05-21	37.470 mi
Registration #19	2019-05-21	37.470 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1967 mm
Height	1586 mm
Length	4034 mm
Wheel base	2482 mm
Kerb weight	1235 kg
Max. allowed weight	1722 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D045046