






report date: 2024-03-28

### General information

Make	AUDI
Model	A3 TDI SPORT DPF
Colour	Silver
Year of manufacture	-
Top speed	138 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.0 mpg
Consumption extra urban	61.0 mpg
Consumption combined	49.0 mpg



CarCheck.co.uk page 1/11



KX07FXK
report date: 2024-03-28

**MOT** history

**Advice** 

MOT test number

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice | Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT test number
627875925775

Result

Advice Tyre worn close to legal limit/worn on edge all (5.2.3 (e))

Advice Front Play in steering rack inner joint(s) both sides

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13 2018-11-30 11:28

MOT test number 754443831904

Result ✓ Passed

MOT #12

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 2/11



(2.4.G.2)

KX07FXK

report date: 2024-03-28

**MOT #11** 2018-02-20 15:04 **MOT** test number 586952413003 Result × Failed **Advice** Front Brake pad(s) wearing thin (3.5.1g) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Offside Headlamp aim beam image obviously incorrect (1.8.A.1b) Fail Offside Front Shock absorber has a serious fluid leak (2.7.3) Fail **Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)Advice Offside Front different to other suspension arm **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b) **Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

MOT #10

MOT test number

Result

MOT #9

2017-03-08 15:13

✓ Passed

2016-03-08 11:31

MOT test number

887867885133

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8 2015-01-31 09:44

MOT test number 356701535030

Result ✓ Passed

**Notice** Engine covers fitted obscuring some components in the engine bay

**Notice** Under-trays fitted obscuring some underside components

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #7 2014-02-07 13:31

**MOT test number** 386788134015

**Result** ✓ Passed

MOT #6 2014-01-31 16:10

**MOT test number** 799611034059

**Result** X Failed

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #5 2013-06-18 17:23

**MOT test number** 445649163158

**Result** 
✓ Passed

MOT #4 2013-01-25 11:44

MOT test number 549895123026

**Result** ✓ Passed

MOT #3 2012-06-25 10:46

**MOT test number** 638627272124

**Result** 
✓ Passed

MOT #2 2011-06-09 12:02

MOT test number 745490561131

**Result** 
✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Osf tyre has cuts in inner sidewall not exposing ply or cords

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT #1 2010-06-09 12:01
MOT test number 982590560143

**Result** ✓ Passed

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



KX07FXK report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	historv
OWNER	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
*********	
***************************************	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



KX07FXK report date: 2024-03-28

#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-06-21
Last registration	2020-11-25
Complete history	See info



Registration #1	2007-06-21	17 mi
Registration #2	2010-06-09	29.827 mi
Registration #3	2011-06-09	39.798 mi
Registration #4	2012-06-25	50.636 mi
Registration #5	2013-01-25	53.873 mi
Registration #6	2013-06-18	57.625 mi
Registration #7	2014-01-31	68.086 mi
Registration #8	2014-02-07	68.116 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.177 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 10/11



report date: 2024-03-28

### Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4286 mm
Wheel base	2578 mm
Kerb weight	1380 kg
Max. allowed weight	1940 kg

## Additional information

· · · · · · · · · · · · · · · · · · ·	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11