





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH EDITION TDI
Colour	Black
Year of manufacture	2013
Top speed	105 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	180 Nm at 2.000 rpm
Engine capacity	1.199 сс
Cylinders	3
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-07

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-05-27
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	9
Total items failed	5

MOT #11	2023-05-17 14:28
MOT test number	888209290543
Result	✓ Passed
Next expiry date	2024-05-27
Advice Offside Front Tyre worn close to legal limit/worn on edge worn inner	edge (5.2.3 (e))

MOT #10	2022-05-16 13:34
MOT test number	736599794614
Result	✓ Passed

Result		√ Passeu
MOT #9		2022-05-16 09:54
MOT test number		315960107956
Result		X Failed
Pass with rectification	Offside Headlamp aim too high (4.1	1.2 (a))
Advice Front Brake disc	worn, pitted or scored, but not serio	ously weakened (1.1.14 (a) (ii))
Fail Offside Front Upper (5.3.4 (b) (ii))	Anti-roll bar linkage ball joint dust co	over no longer prevents the ingress of dirt
Advice Front Brake pad	(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front S	shock absorbers has light misting of c	pil (5.3.2 (b))

CarCheck.co.uk page 3/12



report date: 2024-03-29

Passed

MOT #8 2021-05-28 14:06

MOT test number 995282490088

MOT #7 2021-05-28 13:35

MOT test number 674960958231

Result X Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

MOT #6 2020-12-12 09:41

MOT test number 989944516184

Advice Rear exhaust corroded

Advice Real exhaust combaca

MOT #5 2019-12-07 11:48

MOT test number 206960635603

Result \rightarrow Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

(a) (i))

Result

MOT #4 2018-12-19 08:17

MOT test number 381802868107

Result

Passed

CarCheck.co.uk page 4/12



SY63EAM report date: 2024-03-29

MOT #3	2017-12-16 11:21
MOT test number	326912243240
Result	✓ Passed
MOT #2	2016-12-29 09:35
MOT test number	178262817631
Result	✓ Passed
MOT #1	2016-09-23 15:43
MOT test number	596679649586
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	27 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SY63EAM report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates.	, <u> </u>	
Plate changes See in this check if this VOLKSWAGEN had different number plates.	VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow	
Plate changes See in this check if this VOLKSWAGEN had different number plates.	***************************************	
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
See in this check if this VOLKSWAGEN had different number plates.		More info >
	Plate changes	
Plate since	See in this check if this VOLKSWAGEN had different number plates.	
Plate since	Number of plates	
UK UK	Current registration	UK UK
	Plate since	
Plate since	Current registration	UK UK
	Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-01
Last registration	2023-05-17
Complete history	See info



Registration #1	2013-09-01	25 mi
Registration #2	2016-09-23	35.649 mi
Registration #3	2016-12-29	35.656 mi
Registration #4	2017-12-16	40.600 mi
Registration #5	2018-12-19	45.830 mi
Registration #6	2019-12-07	51.851 mi
Registration #7	2020-12-12	55.345 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



SY63EAM report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1134 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
CarChaelesaule	naga 17/13

CarCheck.co.uk page 12/12

Number of seats	5
Engine number	CFWA366345