



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 COMFORT
Colour	Blue
Year of manufacture	2010
Top speed	119 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	157 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	152 g/km
CO2 label	G





## MOT history

MOT expiry date	2024-08-20
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	56
Total items failed	9

## MOT #18 2023-08-12 10:24

MOT test number 896371632041

Result ✓ Passed

Next expiry date 2024-08-20

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #17 2022-08-18 16:14

MOT test number 884315203541

Result ✓ Passed

- Advice** Rear Coil spring corroded (5.3.1 (b) (i))



MOT #162022-08-18 10:07

MOT test number598529092634

Result

Failed

MAJOR

Nearside Rear All direction indicators incorrect colour (4.4.3 (a))

Advice

Rear Coil spring corroded (5.3.1 (b) (i))

MAJOR

Brake lever has insufficient reserve travel (1.1.2 (a))

MAJOR

Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MAJOR

Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #15**

2022-08-09 08:14

**MOT test number**

842055183516

**Result****✗ Failed**

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush deteriorated (5.3.4 (a) (i))

**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**MAJOR** Nearside Front Side repeater incorrect colour (4.4.3 (a))

**Advice** Rear Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 1.99mm inner edge (5.2.3 (e))

**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush deteriorated (5.3.4 (a) (i))

**Advice** Front Sub-frame corroded but not seriously weakened and suspension components (5.3.3 (b) (i))

**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm 1.58mm (5.2.3 (e))

**Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #14**

2021-08-14 10:04

**MOT test number**

744210631105

**Result****✓ Passed**

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2021-08-10 14:50**MOT test number** 634494690654**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2020-08-19 13:01**MOT test number** 566949256329**Result** ✓ Passed**MOT #11** 2019-08-21 13:38**MOT test number** 213377621099**Result** ✓ Passed**MOT #10** 2018-10-31 12:17**MOT test number** 338992742670**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.1mm / worn inner edge (raised tread) (5.2.3 (e))**Advice** Slight corrosion on fuel tank straps**Advice** Slight corrosion on fuel filler neck/tank breathers

**MOT #9**

2018-10-26 15:03

**MOT test number**

201332216402

**Result**

✗ Failed

**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Exhaust has a major leak of exhaust gases 'flexi pipe' blowing excessively (6.1.2 (a))**Advice** Slight corrosion on fuel tank straps**MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm badly worn inner edge (5.2.3 (e))**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.1mm / worn inner edge (raised tread) (5.2.3 (e))**MAJOR** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt clip came loose / insecure (2.1.3 (g) (ii))**Advice** Slight corrosion on fuel filler neck/tank breathers**MAJOR** Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords damaged outer sidewall (5.2.3 (d) (i))**MOT #8**

2017-10-05 07:35

**MOT test number**

842168917929

**Result**

✓ Passed

**MOT #7** 2017-10-04 12:57**MOT test number** 377821333782**Result** ✗ Failed

- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Stop lamp not working (1.2.1b)

**MOT #6** 2016-09-07 11:27**MOT test number** 471825740808**Result** ✓ Passed

- Advice** Nearside rear tyre on legal limit and misshapen

**MOT #5** 2015-07-14 15:27**MOT test number** 238195895477**Result** ✓ Passed**MOT #4** 2015-07-14 15:27**MOT test number** 358045895148**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Pass with rectification** Offside Headlamp aim too low (1.8)

**MOT #3** 2014-10-01 09:40**MOT test number** 268544974245**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2014-09-30 15:44**MOT test number** 478463774262**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #1** 2013-09-26 16:40**MOT test number** 549579063248**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
20 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	20 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-24
Last registration	2023-08-12
Complete history	<a href="#">See info</a>



Registration #1	2010-09-24	28 mi
Registration #2	2013-09-26	35.826 mi
Registration #3	2014-09-30	42.490 mi
Registration #4	2014-10-01	42.491 mi
Registration #5	2015-07-14	42.741 mi
Registration #6	2016-09-07	54.488 mi
Registration #7	2017-10-04	76.324 mi
Registration #8	2017-10-05	76.324 mi
Registration #9	2018-10-26	89.829 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1775 mm
Height	1480 mm
Length	4245 mm
Wheel base	2650 mm
Kerb weight	1293 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4FCAZ147266