





report date: 2024-03-28

### General information

Make	TOYOTA
Model	PRIUS VVT-I T4
Colour	Blue
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed CVT

### Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-06-13


Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MT08YVD report date: 2024-03-28

MOT history

MOT expiry date	2024-06-22
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	17
Total items failed	0

MOT #14	2023-06-15 10:46
MOT test number	730258335282
Result	✓ Passed
Next expiry date	2024-06-22

MOT #13	2022-06-10 11:58
MOT test number	261518713312
Result	<b>√</b> Passed

MOT #12	2021-06-23 09:57
MOT test number	199140100362
Result	<b>✓</b> Passed

MOT #11	2020-11-12 17:00
MOT test number	214848446829

MOI test	214040440025	
Result	✓ Passed	Į
Advice	Exhaust catalyst and boxes rattle	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #10** 2020-10-30 13:27 **MOT** test number 501839316761 Result **X** Failed **MAJOR** Nearside Headlamp aim not tested (4.1.2 (b)) Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **MAJOR** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b)) **MAJOR** Offside Rear Outer Seat belt installation has cut and/or reworked original webbing webbing cut (10.1 (a)) Advice Exhaust catalyst and boxes rattle Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Headlamp aim not tested (4.1.2 (b)) **MAJOR** Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **MAJOR** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b)) **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #9	2019-10-29 14:26
MOT test number	352337482375
Result	✓ Passed
Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))  Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))	

MOT #8	2018-11-05 12:38
MOT test number	996441227590
Result	<b>✓</b> Passed
MOT #7	2017-10-26 13:50
MOT test number	362894570370
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6	2016-10-21 09:50
MOT test number	143118872650
Result	<b>✓</b> Passed
MOT #5	2015-10-30 14:40
MOT test number	733043717999
Result	<b>✓</b> Passed
MOT #4	2014-11-05 10:21
MOT test number	108369604397
Result	<b>✓</b> Passed
MOT #3	2013-11-08 10:35
MOT test number	466132713364
Result	<b>✓</b> Passed
MOT #2	2012-11-02 09:03
MOT test number	998167402398
Result	<b>✓</b> Passed
MOT #1	2011-08-01 11:37
MOT test number	699563511223
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	22 June 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	59
Band	В
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	
***************************************	
manus .	
***************************************	
************	
	More info >
Plate changes	
Coo in this chook if this TOYOTA had different much on plates	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	UK NE
Fiate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-08-28
Last registration	2023-06-15
Complete history	See info



Registration #1	2008-08-28	23 mi
Registration #2	2011-08-01	41.317 mi
Registration #3	2012-11-02	58.172 mi
Registration #4	2013-11-08	66.090 mi
Registration #5	2014-11-05	71.985 mi
Registration #6	2015-10-30	78.283 mi
Registration #7	2016-10-21	86.810 mi
Registration #8	2017-10-26	94.080 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		11.777 ms
Registration #16		10.777 au

More info >

CarCheck.co.uk page 11/12



MT08YVD report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1325 kg
Max. allowed weight	1725 kg

# Additional information

· · · · · · · · · · · · · · · · · · ·		
Fuel tank capacity	45	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 1NZ5248639