





report date: 2024-03-29

General information

Make	AUDI
Model	A2 SPORT
Colour	Black
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	126 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-06

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT history

MOT test number

142055507421

Result

Next expiry date

Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT test number

S42022272574

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Pass with rectification Front Bumper insecure (6.1.4 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT test number

542269071242

Result

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

MOT #21	2019-10-08 12:18
MOT test number	306056513252
Result	✓ Passed

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #20 2019-10-07 14:43

MOT test number 783163340917

Result X Failed

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Fail
Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #19 2018-10-11 14:01

MOT test number 542101012158

Result
✓ Passed

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #18 2017-10-25 08:24

MOT test number 174260253877

Result \rightarrow Passed

Advice Nearside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #17 2016-09-03 11:37

MOT test number 191972718377

Result ✓ Passed

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #16 2015-09-08 14:35 642986675768 **MOT** test number ✓ Passed Result **Advice** Front Brake pad(s) wearing thin (3.5.1g) **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a) Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Rear Exhaust has a minor leak of exhaust gases silencer.rest of system corroded (7.1.2) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #15		2015-09-08 11:52
MOT test	number	164962274649
Result		★ Failed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	5.1i)
Advice	Rear Exhaust has a minor leak of exhaust gases silencer.rest of system corroded	(7.1.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.2)	1i)
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		
Fail O	ffside Front coil spring broken (2.4.C.1a)	
Pass wit	th rectification Nearside Front position lamp(s) not working (1.1.A.3b)	
Advice (2.5.C.1a)	Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing t	he ingress of dirt

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT test number

Result

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #13 2013-08-22 13:37

MOT test number 307384033229

Result ✓ Passed

MOT test number
995747323281

Result

Rear Fuel system component leaking (7.2.3)

Fail Nearside Front coil spring broken (2.4.C.1a)

Fail Rear registration plate deteriorated (6.3.1d)

Fail Nearside Rear Shock absorber insecure (2.7.2b)

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)


Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/15



report date: 2024-03-29



MOT #9		2011-05-04 11:23
MOT test i	number	475484621119
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)	
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3	3.1a)

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #8 2011-05-04 11:23 **MOT** test number 215574421104 Result × Failed Pass with rectification Nearside Stop lamp not working (1.2.1b) **Advice** Exhaust has part of the system slightly deteriorated (7.1.1a) Nearside Front Shock absorber has a light misting of oil (2.7.3) Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c) Advice Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a) Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice **Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #7 2010-03-05 11:16 **MOT** test number 331174460025 ✓ Passed Result **Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b) Notice Both rear tyres outer walls cracking **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Offside Front Tyre worn close to the legal limit (4.1.E.1) **Advice**

MOT #6

MOT test number

293156369000

Result

Pass with rectification

Nearside Rear Registration plate lamp not working (1.1.C.1d)

Notice

Child seat fitted not allowing full inspection of adult belt

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 8/15



MOT #1

MK53BBV

report date: 2024-03-29

2006-05-25 12:30

MOT #5	2009-	03-07 12:29
MOT test	number 623	3036369033
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Notice	Child seat fitted not allowing full inspection of adult helt	

Notice Child seat fitted not allowing full inspection o	f adult belt
MOT #4	2008-02-25 16:00
MOT test number	192226958448
Result	✓ Passed
MOT #3	2007-02-14 14:18
MOT test number	143845547038
Result	✓ Passed
MOT #2	2006-05-25 12:30
MOT test number	622945846114
Result	✓ Passed

Result	✓ Passed

MOT test number 812335046127

Result × Failed

Pass with rectification Nearside Headlamp aim too low when the centre of the headlamp is below 850mm from the ground (1.6.B2)

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

MK53BBV

report date: 2024-03-29

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report here. More info

Plate changes

More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-09-01
Last registration	2022-06-21
Complete history	See info



Registration #1	2003-09-01	19 mi
Registration #2	2006-05-25	38.392 mi
Registration #3	2007-02-14	42.624 mi
Registration #4	2008-02-25	48.600 mi
Registration #5	2009-03-07	55.328 mi
Registration #6	2010-03-05	62.926 mi
Registration #7	2011-05-04	71.595 mi
Registration #8	2012-08-15	81.450 mi
Registration #9	2013-08-15	88.347 mi
Registration #10	2013-08-22	88.347 mi
Registration #11	2014-09-08	93.910 mi
Registration #12		11.777 es
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 mi
Registration #16		11.777 es
Registration #17		11.177 mi
Registration #18		11.777 es
Registration #19		11.177 mi
Registration #20		11.117 es
Registration #21		11.177 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1890 mm
Height	1553 mm
Length	3826 mm
Wheel base	2405 mm
Kerb weight	895 kg

Additional information

Fuel tank capacity	34
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	BBY 318824 page 15/15