



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Grey
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-10-10
Pictures	30
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-11
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	33
Total items failed	1

MOT #17	2023-10-12 10:53
MOT test number	204892345555
Result	✓ Passed
Next expiry date	2024-10-11
Advice	Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front Bush (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #16**

2023-10-11 09:13

**MOT test number**

728766057976

**Result****✗ Failed****MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front Bush (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn Front Bush (5.3.4 (a) (i))**MOT #15**

2022-10-06 12:48

**MOT test number**

781612237953

**Result****✓ Passed****Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #14** 2021-10-11 15:36**MOT test number** 807594657324**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Undertray fitted**MOT #13** 2020-09-15 10:49**MOT test number** 327747501633**Result** ✓ Passed**MOT #12** 2019-08-14 09:34**MOT test number** 277429321573**Result** ✓ Passed**MOT #11** 2019-08-13 09:48**MOT test number** 628638214848**Result** ✗ Failed**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Obligatory mirror insecure (3.3 (b) (ii))**MOT #10** 2018-07-26 07:51**MOT test number** 815066853514**Result** ✓ Passed

**MOT #9** 2018-07-25 15:18**MOT test number** 232677438842**Result** ✗ Failed**DANGEROUS** Offside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**DANGEROUS** Nearside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2017-07-18 09:46**MOT test number** 992182462285**Result** ✓ Passed**Advice** Both rear tyres bald inner edges**MOT #7** 2016-07-21 10:36**MOT test number** 131672424392**Result** ✓ Passed**MOT #6** 2016-07-19 10:01**MOT test number** 209325398445**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too low (1.8)**MOT #5** 2015-07-27 15:21**MOT test number** 839738505288**Result** ✓ Passed



<b>MOT #4</b>	2014-07-22 13:54
---------------	------------------

<b>MOT test number</b>	175063904218
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2013-07-24 15:42
---------------	------------------

<b>MOT test number</b>	305655503446
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2012-09-10 16:23
---------------	------------------

<b>MOT test number</b>	555994952258
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2011-09-10 12:47
---------------	------------------

<b>MOT test number</b>	696093251267
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	2 rear cabin seats folded down not allowing full inspection of 2 adult seat belts
---------------	---



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
11 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	11 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-10
Last registration	2023-10-12
Complete history	<a href="#">See info</a>



Registration #1	2008-09-10	12 mi
Registration #2	2011-09-10	32.705 mi
Registration #3	2012-09-10	39.329 mi
Registration #4	2013-07-24	43.593 mi
Registration #5	2014-07-22	56.196 mi
Registration #6	2015-07-27	72.213 mi
Registration #7	2016-07-19	87.717 mi
Registration #8	2016-07-21	87.717 mi
Registration #9	2017-07-18	99.848 mi
Registration #10	2018-07-25	109.279 mi
Registration #11	2019-05-20	121.277 mi
Registration #12	2019-05-20	121.277 mi
Registration #13	2019-05-20	121.277 mi
Registration #14	2019-05-20	121.277 mi
Registration #15	2019-05-20	121.277 mi
Registration #16	2019-05-20	121.277 mi
Registration #17	2019-05-20	121.277 mi
Registration #18	2019-05-20	121.277 mi
Registration #19	2019-05-20	121.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE A27658