



report date: 2024-03-29

General information

|                     |                     |
|---------------------|---------------------|
| Make                | MAZDA               |
| Model               | 3 D VENTURE EDITION |
| Colour              | Grey                |
| Year of manufacture | 2013                |
| Top speed           | 116 mph             |
| 0 - 60 mph          | 11.0 seconds        |
| Gearbox             | 6 speed Manual      |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 113 BHP             |
| Max. torque             | 270 Nm at 1.750 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 5.3 mpg             |
| Consumption extra urban | 3.8 mpg             |
| Consumption combined    | 4.3 mpg             |
| CO2 emission            | 115 g/km            |
| CO2 label               | C                   |





## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-11-23 |
| MOT pass rate      | 73 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 3          |
| Total advice items | 8          |
| Total items failed | 4          |

MOT #11 2023-11-20 15:45

MOT test number 596731616112

Result ✓ Passed

Next expiry date 2024-11-23

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2022-11-24 15:38

MOT test number 168189109317

Result ✓ Passed

MOT #9 2021-10-21 13:40

MOT test number 302169336845

Result ✓ Passed

**MOT #8** 2020-08-24 14:20**MOT test number** 676396368664**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2020-08-24 13:06**MOT test number** 321387014302**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2019-08-15 10:34**MOT test number** 952133995590**Result** ✓ Passed**Advice** Offside rear tyre perishing slightly**MOT #5** 2018-08-14 10:23**MOT test number** 525603193536**Result** ✓ Passed**MOT #4** 2018-08-14 10:23**MOT test number** 814147544363**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #3** 2017-08-22 11:49**MOT test number** 716172544715**Result** ✓ Passed



|                                                                                                                                        |                  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------|
| MOT #2                                                                                                                                 | 2017-08-22 09:43 |
| MOT test number                                                                                                                        | 181651662925     |
| Result                                                                                                                                 | ✗ Failed         |
| <div><div>Fail</div>Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)</div> |                  |
| <div><div>Fail</div>Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)</div>  |                  |
| MOT #1                                                                                                                                 | 2016-08-16 11:40 |
| MOT test number                                                                                                                        | 634784502414     |
| Result                                                                                                                                 | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
23 November 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 March             |
| <b>Days left</b>        | 306                             |
| <b>MOT expiry date</b>  | 23 November 2024                |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|                                                |                |
|------------------------------------------------|----------------|
| <b>Vehicle class</b>                           | 49             |
| <b>Band</b>                                    | C              |
| <b>Single payment (12 months)</b>              | £ 35,00,-      |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | £ 36,75,-      |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |      |    |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | BX63OKA    |
| Plate since          | 2024-03-29 |
| Current registration | BX63OKA    |
| Plate since          | 2024-03-29 |

More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 12                       |
| First mileage registration | 2013-09-01               |
| Last registration          | 2023-11-20               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2013-09-01 | 23 mi     |
| Registration #2  | 2016-08-16 | 18.784 mi |
| Registration #3  | 2017-08-22 | 25.569 mi |
| Registration #4  | 2017-08-22 | 25.572 mi |
| Registration #5  | 2018-08-14 | 32.466 mi |
| Registration #6  | 2018-08-14 | 32.466 mi |
| Registration #7  | 2019-08-20 | 39.377 mi |
| Registration #8  | 2019-08-20 | 39.377 mi |
| Registration #9  | 2019-08-20 | 39.377 mi |
| Registration #10 | 2019-08-20 | 39.377 mi |
| Registration #11 | 2019-08-20 | 39.377 mi |
| Registration #12 | 2019-08-20 | 39.377 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 86%                             |
| Children       | 84%                             |
| Pedestrian     | 51%                             |
| Safety systems | 71%                             |
| Overall rating | 77%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1755 mm |
| Height              | 1470 mm |
| Length              | 4460 mm |
| Wheel base          | 2640 mm |
| Kerb weight         | 1309 kg |
| Max. allowed weight | 1830 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 55 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | Y6 357067        |