





report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER SD4 GS
Colour	White
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 kW / 191 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/12



LS14WBE

report date: 2024-03-28

Internet history

Entry 4

Date 2023-07-12

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 3

Date 2023-07-02

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2


Date 2022-06-01

Pictures 62

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-11-05
Pictures	8

Listing price <u>View report</u>

CarCheck.co.uk page 2/12









source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-25	
MOT pass rate	89 %	
MOT passed	8	
Failed MOT tests	1	
Total advice items	11	
Total items failed	1	

MOT #9	2023-06-26 13:34
MOT test number	786480114973
Result	✓ Passed
Next expiry date	2024-06-25

MOT #8	2022-11-09 12:19
MOT test number	301174783046
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7		2021-10-28 08:20
MOT test	number	325772920638
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		5.2.3 (d) (i))
Advice Offside Front Tyre worn close to legal limit/worn on edge 2.3mm (5.2.3 (e))		
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #6 2020-10-29 10:16

MOT test number 233826786573

Advice Child Seat fitted not allowing full inspection of adult belt fitted to rear seats

Advice Engine covers and under trays obscuring some components

MOT #5 2019-10-24 14:49

MOT test number 116791031641

Advice Engine covers and under trays obscuring some components

MOT #4 2019-10-24 14:49

MOT test number 461975070328

Result X Failed

Advice Engine covers and under trays obscuring some components

Pass with rectification Offside Front Direction indicator not working (4.4.1 (a) (ii))

MOT #3 2018-11-08 12:02

MOT test number 979805650733

Result Passed

Advice Engine covers and under trays obscuring some components

MOT #2 2017-11-09 10:01

MOT test number 128998555590

CarCheck.co.uk page 4/12



LS14WBE

report date: 2024-03-28

MOT #1 2017-04-01 10:11

MOT test number 460187178648

Result ✓ Passed

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history		
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to		

	More info	>
Plate changes		
See in this check if this LAND ROVER had different number plates.		
Number of plates		,
Current registration	UK SIE	
Plate since		
Current registration	NE NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-28
Last registration	2023-06-26
Complete history	See info



Registration #1	2014-03-28	7 mi
Registration #2	2017-04-01	43.937 mi
Registration #3	2017-11-09	52.423 mi
Registration #4	2018-11-08	65.410 mi
Registration #5	2019-10-24	78.692 mi
Registration #6	2019-10-24	78.692 mi
Registration #7	2020-10-29	89.090 mi
Registration #8		7.77
Registration #9		77.777 46
Registration #10		77.777 46
Registration #11		77.777 46
Registration #12		77.777 46
Registration #13		77,777 46

7070.70.70

More info >

77.777 86

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****

Video <u>see crash video</u>



Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1745 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DZ784181354224DT

CarCheck.co.uk page 12/12