



PJIIXXN

report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER S ALL4
Colour	Red
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	157 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-10-12
Pictures	20
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-03
Pictures	5
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-10-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #13	2023-10-09 08:05
MOT test number	586710173662
Result	✓ Passed
Next expiry date	2024-10-21

MOT #12	2022-10-17 07:43
MOT test number	625970555284
Result	✓ Passed

MOT #11	2021-10-22 08:01
MOT test number	261607680565
Result	✓ Passed

MOT #10	2021-10-21 14:52
MOT test number	450438338848
Result	✗ Failed
Fail	Offside Front Outer Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Front Outer Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #9	2020-08-20 15:06
MOT test number	843767351844
Result	✓ Passed

**MOT #8** 2019-09-11 16:39**MOT test number** 176544029318**Result** ✓ Passed**MOT #7** 2019-07-09 16:06**MOT test number** 132555531976**Result** ✓ Passed**MOT #6** 2018-06-19 09:09**MOT test number** 648698851665**Result** ✓ Passed

- Advice** Nearside Front strut top mount starting to separate
- Advice** Under cover fitted
- Advice** Offside Rear Brake cable damaged but not to excess (1.1.15 (a))
- Advice** Offside Front strut top mount starting to separate

MOT #5 2017-06-20 12:22**MOT test number** 414259775167**Result** ✓ Passed**MOT #4** 2016-06-04 09:31**MOT test number** 769450345292**Result** ✓ Passed

- Advice** Under trays fitted
- Advice** Small hole in o/s/f ball joint rubber boot



MOT #3	2016-06-04 09:31
MOT test number	675001244388
Result	✗ Failed
Advice	Under trays fitted
Pass with rectification	Nearside Headlamp aim too high (1.8)
Advice	Small hole in o/s/f ball joint rubber boot

MOT #2	2015-06-05 12:15
MOT test number	247136855483
Result	✓ Passed

MOT #1	2014-06-13 09:01
MOT test number	967324664126
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
21 October 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	21 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	XX11XX
Plate since	2024-03-29
Current registration	XX11XX
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-06-29
Last registration	2023-10-09
Complete history	See info



Registration #1	2011-06-29	11 mi
Registration #2	2014-06-13	19.002 mi
Registration #3	2015-06-05	23.513 mi
Registration #4	2016-06-04	30.163 mi
Registration #5	2016-06-04	30.163 mi
Registration #6	2017-06-20	36.628 mi
Registration #7	2018-06-19	42.647 mi
Registration #8	2019-07-09	50.940 mi
Registration #9	2020-06-29	55.277 mi
Registration #10	2021-06-29	55.277 mi
Registration #11	2022-06-29	55.277 mi
Registration #12	2023-06-29	55.277 mi
Registration #13	2024-06-29	55.277 mi
Registration #14	2025-06-29	55.277 mi
Registration #15	2026-06-29	55.277 mi
Registration #16	2027-06-29	55.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1380 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	A353I970