



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Black
Year of manufacture	2009
Top speed	125 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 2

Date	2021-06-08
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-05-24
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-21
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	18
Total items failed	5

MOT #15	2024-04-22 10:44
MOT test number	700163179668
Result	✓ Passed
Next expiry date	2025-04-21
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #14	2024-04-19 09:13
MOT test number	734425556030
Result	✗ Failed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Headlamp levelling device cannot be operated from the driver's seat (4.1.5 (b))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Headlamp aim too low (4.1.2 (a))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Nearside Headlamp aim too low (4.1.2 (a))

**MOT #13** 2022-11-29 11:23**MOT test number** 572765782371**Result** ✓ Passed**Advice** Front suspension sub frame/suspension components surface corroded**Advice** Rear brake pads starting to wear low (nearside)**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Brake disc surfaces corroded - due to lack of use**Advice** Rear suspension sub frame /suspension arms/ components surface corroded**MOT #12** 2021-03-30 10:28**MOT test number** 654827515829**Result** ✓ Passed**MOT #11** 2020-11-24 09:49**MOT test number** 424571937215**Result** ✓ Passed**MOT #10** 2019-11-01 16:08**MOT test number** 704429757742**Result** ✓ Passed**MOT #9** 2018-11-07 15:24**MOT test number** 702352955035**Result** ✓ Passed**MOT #8** 2017-11-14 11:12**MOT test number** 811172197597**Result** ✓ Passed

**MOT #7** 2017-11-13 14:32**MOT test number** 904496584597**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-11-17 10:30**MOT test number** 353199593166**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-11-19 17:01**MOT test number** 612071764237**Result** ✓ Passed**MOT #4** 2014-11-05 16:49**MOT test number** 317619504389**Result** ✓ Passed**MOT #3** 2014-11-05 09:59**MOT test number** 227379204352**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Notice** Both rear tures wearing uneven



MOT #2	2013-11-22 12:15
MOT test number	567496323302
Result	✓ Passed

MOT #1	2012-11-28 12:14
MOT test number	776273032380
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
21 April 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	21 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	 <b>KR59VST</b>
Plate since	2024-03-29
Current registration	 <b>KR59VST</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-22
Last registration	2024-04-22
Complete history	<a href="#">See info</a>



Registration #1	2009-12-22	20 mi
Registration #2	2012-11-28	28.224 mi
Registration #3	2013-11-22	31.840 mi
Registration #4	2014-11-05	38.030 mi
Registration #5	2014-11-05	38.031 mi
Registration #6	2015-11-19	42.527 mi
Registration #7	2016-11-17	45.430 mi
Registration #8	2017-11-13	49.833 mi
Registration #9	2017-11-14	49.833 mi
Registration #10	2018-11-14	54.236 mi
Registration #11	2018-11-14	54.237 mi
Registration #12	2018-11-14	54.237 mi
Registration #13	2018-11-14	54.237 mi
Registration #14	2018-11-14	54.237 mi
Registration #15	2018-11-14	54.237 mi
Registration #16	2018-11-14	54.237 mi
Registration #17	2018-11-14	54.237 mi
Registration #18	2018-11-14	54.237 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1605 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	090622085755BG