



report date: 2024-03-29

General information

Make	KIA
Model	CEED CRDI 3 ECODYNAMICS
Colour	White
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-06-15
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-31
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	27
Total items failed	8

MOT #12 2023-08-15 15:05

MOT test number 875913650866

Result ✓ Passed

Next expiry date 2024-08-31

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #11 2022-08-17 08:39

MOT test number 744767617542

Result ✓ Passed

MOT #10 2021-09-01 12:01

MOT test number 282059428440

Result ✓ Passed

**MOT #9** 2021-08-31 10:17**MOT test number** 327691546933**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Lower Sub-frame ball joint excessively worn (5.3.4 (a) (i))**MOT #8** 2020-06-13 09:02**MOT test number** 490627033873**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Inner wheel arch missing**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #7** 2020-06-11 08:40**MOT test number** 912167350725**Result** ✗ Failed**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Nail in tyre**Advice** Offside Front Inner wheel arch missing**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2019-05-22 12:00**MOT test number** 289833664388**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #5** 2018-05-29 15:31**MOT test number** 757005274465**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2017-05-30 15:29**MOT test number** 477051993229**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #3** 2017-05-29 11:28**MOT test number** 676980694579**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #2** 2016-05-31 10:29**MOT test number** 483064043844**Result** ✓ Passed**MOT #1** 2015-12-23 09:37**MOT test number** 755332106972**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
31 August 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	31 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history


Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>LB62PNN</b>
Plate since	2024-03-29
Current registration	<b>LB62PNN</b>
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-12-31
Last registration	2023-08-15
Complete history	<a href="#">See info</a>



Registration #1	2012-12-31	28 mi
Registration #2	2015-12-23	35.234 mi
Registration #3	2016-05-31	37.763 mi
Registration #4	2017-05-29	50.136 mi
Registration #5	2017-05-30	50.136 mi
Registration #6	2018-05-29	61.556 mi
Registration #7	2019-05-22	76.512 mi
Registration #8	2019-05-22	76.512 mi
Registration #9	2019-05-22	76.512 mi
Registration #10	2019-05-22	76.512 mi
Registration #11	2019-05-22	76.512 mi
Registration #12	2019-05-22	76.512 mi
Registration #13	2019-05-22	76.512 mi
Registration #14	2019-05-22	76.512 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1499 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

D4FBCZ423157