



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO 16V DYNAMIC SPORT
Colour	Red
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	125 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-18
Pictures	11
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #17**

2021-06-12 09:10

MOT test number

524876926735

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside mirror cover missing
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))
- Advice** Central stop lamp less than 50 operative

MOT #16

2020-11-20 16:56

MOT test number

992031829117

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases front pipe (6.1.2 (a))

MOT #15

2019-05-21 08:18

MOT test number

711670800161

Result**✓ Passed**

- Advice** Front Macpherson strut damaged but not seriously weakened both (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14** 2017-12-11 13:15**MOT test number** 576259156510**Result** ✓ Passed**Advice** Oil leaks**Advice** Nearside sill panel has damage.**MOT #13** 2017-12-11 13:15**MOT test number** 377312190061**Result** ✗ Failed**Advice** Oil leaks**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Nearside sill panel has damage.**MOT #12** 2016-12-15 16:25**MOT test number** 119334309638**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** All four tyres have age cracks**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside sill damaged**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #11**

2016-12-15 10:47

MOT test number

916151649594

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** All four tyres have age cracks
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
- Advice** Nearside sill damaged

MOT #10

2016-01-08 12:30

MOT test number

977514221370

Result**✓ Passed**

- Advice** All four tyres have minute aged cracks between treads
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #9

2016-01-08 12:30

MOT test number

760971186375

Result**✗ Failed**

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Pass with rectification** Front Headlamp aim too low both (1.8)
- Advice** All four tyres have minute aged cracks between treads
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2015-01-08 14:46**MOT test number** 277338605081**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Nearside sill panel damaged**MOT #7** 2014-01-09 15:09**MOT test number** 757679704048**Result** ✓ Passed**MOT #6** 2013-01-11 11:34**MOT test number** 856771013046**Result** ✓ Passed**MOT #5** 2013-01-10 12:33**MOT test number** 915620013005**Result** ✗ Failed**Fail** Nearside Front coil spring incomplete (2.4.C.1a)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front coil spring incomplete (2.4.C.1a)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2012-01-04 11:37**MOT test number** 309434102097**Result** ✓ Passed



MOT #3	2012-01-04 11:37
MOT test number	975574402038
Result	✗ Failed
Pass with rectification	Nearside Front All position lamps not working (1.1.A.3b)
Pass with rectification	Offside Rear All position lamps not working (1.1.A.3b)

MOT #2	2010-12-21 11:21
MOT test number	482915950391
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-12-15 13:40
MOT test number	401859649329
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-01-05
Last registration	2021-06-12
Complete history	See info



Registration #1	2007-01-05	25 mi
Registration #2	2009-12-15	16.435 mi
Registration #3	2010-12-21	23.000 mi
Registration #4	2012-01-04	28.234 mi
Registration #5	2013-01-10	34.318 mi
Registration #6	2013-01-11	34.318 mi
Registration #7	2014-01-09	37.527 mi
Registration #8	2015-01-08	38.786 mi
Registration #9	2016-01-08	41.284 mi
Registration #10	2016-01-08	41.284 mi
Registration #11	2016-01-08	41.284 mi
Registration #12	2016-01-08	41.284 mi
Registration #13	2016-01-08	41.284 mi
Registration #14	2016-01-08	41.284 mi
Registration #15	2016-01-08	41.284 mi
Registration #16	2016-01-08	41.284 mi
Registration #17	2016-01-08	41.284 mi
Registration #18	2016-01-08	41.284 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1060 kg
Max. allowed weight	2635 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1134831