





report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA HDI EXCLUSIVE PICASSO
Colour	Silver
Year of manufacture	2003
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 1

Date 2021-11-01

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-28
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	21
Total items failed	17

MOT #25	2024-01-29 10:20
MOT test number	749795443118
Result	✓ Passed
Next expiry date	2025-01-28
Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #24	2023-01-16 12:33
MOT test number	408004293943
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #23	2023-01-16 10:52
MOT test number	970036981823
Result	× Failed
Fail Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents th	ne ingress of dirt (5.3.4 (b)
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/15



Result

AO53PYW

report date: 2024-03-28

× Failed

MOT #22 2022-01-13 18:08

MOT test number 848354614999

Result ✓ Passed

Advice Front Lower Oil leak, but not excessive (8.4.1 (a) (i))

MOT #21 2021-12-13 15:42

MOT test number 213960350713

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Rear EXHAUST CORRODING

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Minor Offside Obligatory mirror slightly loose (3.3 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #20 2021-01-27 14:59

MOT test number 179692385015

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #	19	2021-01-26 16:35
MOT te	est number	942497398151
Result		× Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #	18	2020-01-29 15:31
MOT te	est number	399691595697
Result		✓ Passed
MOT #	17	2020-01-29 12:53
MOT te	est number	125710950950
Result		X Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

Nearside Front Brake pad(s) less than 1.5 min thick (1.1.15 (a) (ii))	
MOT #16	2019-01-24 16:25
MOT test number	327079691545
Result	✓ Passed
MOT #15	2017-10-20 10:59
MOT test number	155784008404
Result	✓ Passed
MOT #14	2016-10-21 09:27
MOT test number	394134006057
Result	✓ Passed

CarCheck.co.uk page 5/15



report date: 2024-03-28

 MOT #13
 2015-10-23 09:41

 MOT test number
 924218320863

Result ✓ Passed

MOT #12 2014-10-08 12:58

MOT test number 568111784274

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #11 2013-10-02 12:48

MOT test number 587135773204

Result \rightarrow Passed

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

MOT #10 2012-10-02 16:16

MOT test number 529006972219

Result \rightarrow Passed

MOT #9 2012-10-01 14:28

MOT test number 129115972294

Result × Failed

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

Notice Offside front tyre cut in places, but not outside acceptable limits

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #8 2011-09-19 10:32

MOT test number 308862361458

Result
✓ Passed

MOT #7 2011-09-19 10:32

MOT test number 609802961234

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #6 2010-09-29 13:07

MOT test number 551612670292

Result \rightarrow Passed

MOT #5 2009-10-05 12:32

MOT test number 200108079258

Result
✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #4 2008-10-10 08:56

MOT test number 702894488260

Result ✓ Passed

MOT #3 2008-10-09 14:49

MOT test number 493933188293

Result × Failed

Fail Centre Rear Seat belt affected by an insecure seat fixing (5.2.1b)

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #2

MOT test number

Result

Notice Child seat fitted not allowing full inspection of adult belt

MOT #1	2006-09-28 10:27
MOT test number	373351876416
Result	✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

_	
Owner	history
OWITCH	HISCOLY

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here.	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Francis and bullion	
Cornect registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >
	Piore IIII0 /

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-09-30
Last registration	2024-01-29
Complete history	See info



Registration #1	2003-09-30	29 mi
Registration #2	2006-09-28	18.759 mi
Registration #3	2007-10-01	24.606 mi
Registration #4	2008-10-09	28.918 mi
Registration #5	2008-10-10	28.920 mi
Registration #6	2009-10-05	31.922 mi
Registration #7	2010-09-29	34.682 mi
Registration #8	2011-09-19	36.969 mi
Registration #9	2012-10-01	39.205 mi
Registration #10	2012-10-02	39.210 mi
Registration #11	2013-10-02	41.153 mi
Registration #12	2014-10-08	43.283 mi
Registration #13	2015-10-23	46.155 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		71.777 es
Registration #25		11.777 es
Registration #26		11.777 es

CarCheck.co.uk page 14/15



report date: 2024-03-28

Safety ratings

NCAP rating	****	

Video <u>see crash video</u>

Dimensions & weight

Width	1752 mm
Height	1625 mm
Length	4267 mm
Wheel base	2760 mm
Kerb weight	1300 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DYLP3037355

CarCheck.co.uk page 15/15