



General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Blue
Year of manufacture	2010
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-12
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-09
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	43
Total items failed	5

MOT #14 2024-01-11 18:48

MOT test number 796377617366

Result ✓ Passed

Next expiry date 2025-02-09

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Suspension arm corroded but not seriously weakened rear suspension corroded (5.3.3 (b) (i))

MOT #13 2024-01-10 14:35

MOT test number 706387748220

Result ✗ Failed**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Suspension arm corroded but not seriously weakened rear suspension corroded (5.3.3 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12 2023-01-12 15:21

MOT test number 816162364601

Result ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11**

2022-01-20 16:40

MOT test number

615183122508

Result

✓ Passed

Advice Engine covers and under trays fitted**Advice** Heavy oil leak around turbo area,**Advice** Rear exhaust heat shield insecure**MOT #10**

2022-01-20 08:12

MOT test number

110461118384

Result

✗ Failed

Advice Rear exhaust heat shield insecure**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Fail** Offside Front Brake disc significantly and obviously worn inner face (1.1.14 (a) (i))**Advice** Engine covers and under trays fitted**Fail** Exhaust emissions exceed manufacturer's specified limit plate limit 1.51 (8.2.2.2 (a))**Advice** Nearside Front Brake disc worn, but not excessively inner face (1.1.14 (a) (i))**Advice** Heavy oil leak around turbo area,**MOT #9**

2021-02-04 09:44

MOT test number

845372634226

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive under tray fitted (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2020-02-04 14:32

MOT test number

146588570963

Result

✓ Passed

- Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))
- Advice** Surface corrosion to suspension components
- Advice** Nearside Front Daytime light not working
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Seat slightly insecure
- Advice** Corrosion and slight leak from rear of exhaust

MOT #7

2019-02-08 14:32

MOT test number

692536300828

Result

✓ Passed

- Advice** Nearside Front Driving lamp inop
- Advice** General corrosion on suspension components
- Advice** Rear Trailing arm bushes de-bonding
- Advice** Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))

MOT #6

2018-02-09 11:53

MOT test number

384220527580

Result

✓ Passed

- Advice** Oil leak Engine.
- Advice** Nearside Front Driving light not working.
- Advice** Under-trays fitted not allowing full inspection of underside of vehicle.

**MOT #5** 2017-01-19 11:29**MOT test number** 154176658245**Result** ✓ Passed**Advice** Oil leak**Advice** Centre rear seat belt buckle incorrect as button need to be pushed down to clip belt buckle in. but still functioning**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt pin holed (2.4.G.2)**Advice** Both front tyres worn on edges**MOT #4** 2016-02-05 09:19**MOT test number** 358773395169**Result** ✓ Passed**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2015-02-10 11:38**MOT test number** 807811045013**Result** ✓ Passed**Advice** Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** O/s/f seat slightly insecure**MOT #2** 2013-11-19 10:37**MOT test number** 236573323367**Result** ✓ Passed**Notice** Cut in n/s/f tyre outer side wall.**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #1	2013-11-19 10:37
MOT test number	549663823392
Result	✗ Failed
Pass with rectification	Offside Side repeater not working (1.4.A.2c)
Notice	Cut in n/s/f tyre outer side wall.
Notice	Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	BT10AVB
Plate since	2019-03-28
Current registration	BT10AVB
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-07-14
Last registration	2024-01-11
Complete history	See info



Registration #1	2010-07-14	8 mi
Registration #2	2013-11-19	55.377 mi
Registration #3	2015-02-10	69.502 mi
Registration #4	2016-02-05	77.152 mi
Registration #5	2017-01-19	83.263 mi
Registration #6	2018-02-09	89.436 mi
Registration #7	2019-02-08	95.999 mi
Registration #8	2020-02-04	105.224 mi
Registration #9	2021-02-04	111.377 mi
Registration #10	2022-02-04	117.530 mi
Registration #11	2023-02-04	123.683 mi
Registration #12	2024-01-11	129.836 mi
Registration #13	2024-01-11	135.989 mi
Registration #14	2024-01-11	142.142 mi
Registration #15	2024-01-11	148.295 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1743 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	AU23978