





report date: 2024-03-29

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC4 8 SEATS
Colour	Beige
Year of manufacture	2004
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	343 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.6 mpg
Consumption extra urban	32.5 mpg
Consumption combined	27.2 mpg
CO2 emission	277 g/km
CO2 label	М



CarCheck.co.uk page 1/13




Internet history

Entry 1

Date 2021-09-08

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2022-09-12
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	6
Total items failed	5

MOT #17	2021-09-13 10:26
MOT test number	429855024346
Result	✓ Passed
Next expiry date	2022-09-12

MOT #16		2020-12-09 09:44
MOT test	number	274300825179
Result		✓ Passed
Advice	General surface corrosion to all underside components/areas	
Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))		

CarCheck.co.uk page 3/13



MOT #15

YT54XMH
report date: 2024-03-29

2020-11-25 10:23

MOT test number 968102881867

Result X Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Offside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt upper arm (5.3.4 (b) (ii))

Fail
Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice General surface corrosion to all underside components/areas

Fail Nearside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt upper arm (5.3.4 (b) (ii))

MOT #14 2019-06-11 10:58

MOT test number 837074486193

Result \square Passed

MOT #13 2019-06-10 14:59

MOT test number 583648416348

Result × Failed

Fail Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #12 2018-10-17 17:07

MOT test number 569591788246

Result \square Passed

MOT #11 2017-09-07 17:47

MOT test number 700127918081

Result

Passed

CarCheck.co.uk page 4/13



MOT #10	2016-08-11 15:56
MOT test number	119565516319
Result	✓ Passed
MOT #9	2015-09-03 10:19
MOT test number	613451086161
Result	✓ Passed
MOT #8	2014-08-30 14:41
MOT test number	369402944227
Result	✓ Passed
MOT #7	2013-09-10 16:32
MOT test number	959413553224
Result	✓ Passed
	2012 00 12 10 20
MOT #6	2012-08-13 18:38
MOT test number	199896922281
Result	✓ Passed
MOT #5	2011-09-02 16:17
MOT test number	348855441451
Result	✓ Passed
Result	√ rasseu
MOT #4	2010-08-31 19:47
MOT test number	550203140284
Result	✓ Passed
MOT #3	2009-09-01 19:04
MOT test number	800584549209
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #2	2008-08-22 19:27
MOT test number	770895238258
Result	✓ Passed
MOT #1	2007-08-21 18:52
MOT test number	690733537218
Result	✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check

X Untaxed

Tax expired: 30 November 2021

X MOT

Expired: 12 September 2022

Tax status Expired at 30 November 2021

Days left 882 days too late

MOT expiry date 12 September 2022

Full MOT history See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when miscory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes See in this check if this TOYOTA had different number plates.	
See in this eneck is this 1919 in that amerene names places	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK ZIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-09-01
Last registration	2021-09-13
Complete history	See info



Registration #1	2004-09-01	16 mi
Registration #2	2007-08-21	25.206 mi
Registration #3	2008-08-22	33.971 mi
Registration #4	2009-09-01	37.141 mi
Registration #5	2010-08-31	42.890 mi
Registration #6	2011-09-02	44.654 mi
Registration #7	2012-08-13	49.576 mi
Registration #8	2013-09-10	54.420 mi
Registration #9	2014-08-30	56.702 mi
Registration #10	2015-09-03	62.107 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1990 kg

Additional information

Fuel tank capacity	87
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Engine number	1KD1121289

CarCheck.co.uk page 13/13