





report date: 2024-03-28

### General information

Make	FIAT
Model	500 C TWINAIR PLUS
Colour	Red
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	Α



CarCheck.co.uk page 1/13



## Internet history

### Entry 2

Date	2023-04-29
Pictures	0
Listing price	View report

#### source: carcraft.co.uk


#### Entry 1

Date	2021-01-21	
Pictures	16	
Listing price	View report	









source: yesauto.com

CarCheck.co.uk page 2/13



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-14
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	21
Total items failed	5

MOT #12	2023-11-15 10:58
MOT test number	323191144581
Result	✓ Passed
Next expiry date	2024-11-14

MOT #11	2023-01-18 12:16
MOT test number	927429633120
Result	<b>√</b> Passed

MOT #10	2022-01-17 11:21
MOT test number	701773393639
Result	<b>✓</b> Passed
Advice Nsr tyre close to legal limit	

MOT #9	2021-01-19 11:19
MOT test number	777260890077
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #8 2021-01-12 15:57

**MOT test number** 842129761554

**Result** X Failed

Fail Nearside Front Suspension arm pin or bush excessively worn bush to rear of arm (debonded (5.3.4 (a) (i))

Advice Nearside Front McPherson strut top mount has slight play

Fail Offside Front Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened very worn and corroded on inner face (1.1.14 (a) (ii))

Advice Offside Front Macpherson strut corroded but not seriously weakened top (5.3.3 (b) (i))

Advice Offside Front Brake pad(s) wearing thin approx 2mm (1.1.13 (a) (ii))

Fail Windscreen washer not working both nearside and offside (3.5 (a))

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened very worn and corroded on inner face (1.1.14 (a) (ii))

Advice Nearside Front Macpherson strut corroded but not seriously weakened top (5.3.3 (b) (i))

Advice Nearside Front Brake pad(s) wearing thin approx 2mm (1.1.13 (a) (ii))

MOT #7 2020-02-08 08:57

MOT test number 329399871212

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



MOT #6 2019-02-22 11:55

MOT test number 107858818101

**Result** 
✓ Passed

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #5** 2019-02-19 15:34

**MOT test number** 760220073254

**Result** X Failed

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #4 2018-05-29 09:23

MOT test number 832607722418

Result 

Passed

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #3 2017-05-12 07:51

MOT test number 533611584152

Advice Nearside Front Tyre worn close to the legal limit strong advisory on inner edge (4.1.E.1)

Advice Offside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

MOT #2 2016-05-23 10:40

MOT test number 838273953271

**Result** ✓ Passed

Advice Slight exhaust blow

CarCheck.co.uk page 5/13



MOT #1 2015-05-28 11:28

**MOT test number** 288518245498

**Result** ✓ Passed

CarCheck.co.uk page 6/13





## Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	14 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
*********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	ZIE UK
Plate since	
Current registration	EK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-31
Last registration	2023-11-15
Complete history	See info



Registration #1	2012-05-31	21 mi
Registration #2	2015-05-28	16.720 mi
Registration #3	2016-05-23	20.356 mi
Registration #4	2017-05-12	25.629 mi
Registration #5	2018-05-29	30.740 mi
Registration #6	2019-02-19	30.971 mi
Registration #7	2019-02-22	30.974 mi
Registration #8	2020-02-08	36.604 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		
3		

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/1.

Number of axles 2

Engine number 0054800