



KR64V NK

report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D3 SE LUX
Colour	Silver
Year of manufacture	2014
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-12
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-26
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #8	2023-08-18 12:22
MOT test number	660416858864
Result	✓ Passed
Next expiry date	2024-08-26
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #7	2022-08-04 12:52
MOT test number	678608312975
Result	✓ Passed

MOT #6	2021-08-27 12:43
MOT test number	385394866941
Result	✓ Passed

**MOT #5**

2021-08-27 10:59

**MOT test number**

165184666296

**Result**

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Power steering close to minimum mark (2.1.5 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge very low (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge very low (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4**

2021-08-23 13:52

**MOT test number**

611435494454

**Result**

✗ Failed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge very low (5.2.3 (e))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Power steering close to minimum mark (2.1.5 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge very low (5.2.3 (e))

**MOT #3**

2020-09-08 08:46

**MOT test number**

126138073153

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt



MOT #2	2019-09-14 10:43
MOT test number	529194222392
Result	✓ Passed

MOT #1	2018-10-01 10:45
MOT test number	650500866365
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
26 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	26 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KR64VNK
Plate since	2024-03-29
Current registration	KR64VNK
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-12-18
Last registration	2023-08-18
Complete history	<a href="#">See info</a>



Registration #1	2014-12-18	25 mi
Registration #2	2018-10-01	69.221 mi
Registration #3	2019-09-14	83.427 mi
Registration #4	2020-09-08	95.960 mi
Registration #5	2021-08-20	101.277 mi
Registration #6	2022-08-20	101.277 mi
Registration #7	2022-08-20	101.277 mi
Registration #8	2022-08-20	101.277 mi
Registration #9	2022-08-20	101.277 mi
Registration #10	2023-08-18	101.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2106 mm
Height	1547 mm
Length	4814 mm
Wheel base	2816 mm
Kerb weight	1736 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1530171