





report date: 2024-03-28

### General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Blue
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



# Internet history

Entry	1
-------	---

Lifety 1	
Date	2021-06-23
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



### MOT history

MOT expiry date	2024-07-20
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #7	2023-07-10 10:48
MOT test number	920389029374
Result	<b>✓</b> Passed
Next expiry date	2024-07-20

CarCheck.co.uk page 3/12



**RO14XVL** 

report date: 2024-03-28

MOT #6	2022-06-27 10:08
MOT test number	556242377379
Result	✓ Passed
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Items removed from driver's view prior to test	
Advice Engine bay covers obscuring testable components & prescribed are	eas
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)	)
<b>Advice</b> Parking brake lever defective but can be satisfactorily operated ve adjustment/inspection (1.1.6 (d))	ery little reserve travel, requires
Advice Brake pedal wearing smooth anti-slip rubber worn on edge (1.1.2 (	(c))
Advice Nearside Washer jet blocked	
Minor Nearside Side repeater with a multiple light source up to 1/2 not fur	nctioning (4.4.1 (a) (i))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (	e))
Advice Under trays/covers obscuring testable components	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing old 201	.3 y o m (5.2.3 (d) (ii))
Advice Parking brake efficiency only just met. It would appear that the braadjustment or repair. 18% on roller brake test (1.4.2 (a) (i))	aking system requires
Advice Offside Rear Parking brake slightly low effort on roller brake test, re	equires adjustment/inspection

MOT #5	2021-06-29 07:48
MOT test number	278550636130
Result	<b>✓</b> Passed
MOT #4	2020-07-21 11:33
MOT test number	548633729379
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



**MOT test number** 

RO14XVL report date: 2024-03-28

495410997617

MOT #3	2019-04-18 13:28

MOT #2 2018-04-20 15:03
MOT test number 169655247825

**Result** ✓ Passed

MOT #1 2017-04-27 07:15

**MOT test number** 392496364257

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	20 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12




**RO14XVL** 

report date: 2024-03-28

#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when mistery	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK LINE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-04-28
Last registration	2023-07-10
Complete history	See info



Registration #1	2014-04-28	21 mi
Registration #2	2017-04-27	38.142 mi
Registration #3	2018-04-20	48.261 mi
Registration #4	2019-04-18	60.198 mi
Registration #5	2020-07-21	69.786 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

The HYUNDAI factory car options list is only available in the premium report.			
S0225	Air conditioning		
S0295			
S0482			
S0501			
S0566			
S0567			

View the complete HYUNDAI factory list for this vehicle <a href="here">here</a>.

More info >

# Safety ratings

**S0569** 

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

### Additional information

Fuel tank capacity	58 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	age 12/12

Number of axles 2

**Engine number** D4FDEZ258681