



HONDA



OWI8LUB

report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | HONDA          |
| Model               | HR-V I-VTEC SE |
| Colour              | Blue           |
| Year of manufacture | 2018           |
| Top speed           | 119 mph        |
| 0 - 60 mph          | 10.4 seconds   |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 128 BHP             |
| Max. torque             | 155 Nm at 4.600 rpm |
| Engine capacity         | 1.498 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 39.8 mpg            |
| Consumption extra urban | 57.6 mpg            |
| Consumption combined    | 49.6 mpg            |
| CO2 emission            | 134 g/km            |
| CO2 label               | E                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-11-09                  |
| Pictures      | 16                          |
| Listing price | <a href="#">View report</a> |



source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-08-23 |
| MOT pass rate      | 75 %       |
| MOT passed         | 3          |
| Failed MOT tests   | 1          |
| Total advice items | 5          |
| Total items failed | 1          |

|                  |  |
|------------------|--|
| MOT #4           | 2023-08-22 08:48   |
| MOT test number  | 967051295981   |
| Result           | ✓ Passed   |
| Next expiry date | 2024-08-23   |
| Advice           | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice           | Offside Rear tyre outer wall perished                                |

|                 |   |
|-----------------|---|
| MOT #3          | 2022-08-24 11:52  |
| MOT test number | 853772441470  |
| Result          | ✓ Passed  |
| Advice          | Rear Child Seat fitted not allowing full inspection of adult belt |

|                 |   |
|-----------------|---|
| MOT #2          | 2022-08-24 08:43  |
| MOT test number | 197866106150  |
| Result          | ✗ Failed  |
| Fail            | Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Advice          | Rear Child Seat fitted not allowing full inspection of adult belt         |



|                 |  |
|-----------------|--|
| MOT #1          | 2021-07-07 10:14   |
| MOT test number | 141697081623   |
| Result          | ✓ Passed   |
| Advice          | Nearside Rear Tyre worn close to legal limit/worn on edge Close to legal limit (5.2.3 (e)) |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
23 August 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 March             |
| <b>Days left</b>        | 305                             |
| <b>MOT expiry date</b>  | 23 August 2024                  |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|                                      |            |
|--------------------------------------|------------|
| <b>Vehicle class</b>                 | 48         |
| <b>Band</b>                          | H          |
| <b>First licence fee (12 months)</b> | £ 255,00,- |
| <b>Standard rate (12 months)</b>     | £ 180,00,- |
| <b>Standard rate (6 months)</b>      | £ 99,00,-  |
| <b>Premium rate (12 months)</b>      | £ 570,00,- |
| <b>Premium rate (6 months)</b>       | £ 313,50,- |



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,299 |
| Auction value               | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |      |    |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this HONDA had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>XXXX XX</b> |
| Plate since          | 2024-03-29     |
| Current registration | <b>XXXX XX</b> |
| Plate since          | 2024-03-29     |

More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 6                        |
| First mileage registration | 2018-07-09               |
| Last registration          | 2023-08-22               |
| Complete history           | <a href="#">See info</a> |



|                 |            |           |
|-----------------|------------|-----------|
| Registration #1 | 2018-07-09 | 23 mi     |
| Registration #2 | 2021-07-07 | 21.276 mi |
| Registration #3 | 2022-05-20 | 25,277 mi |
| Registration #4 | 2022-05-20 | 25,277 mi |
| Registration #5 | 2022-05-20 | 25,277 mi |
| Registration #6 | 2023-08-22 | 25,277 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 86%                             |
| Children       | 79%                             |
| Pedestrian     | 72%                             |
| Safety systems | 71%                             |
| Overall rating | 79%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2019 mm |
| Height              | 1605 mm |
| Length              | 4294 mm |
| Wheel base          | 2610 mm |
| Kerb weight         | 1313 kg |
| Max. allowed weight | 1790 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Engine number      | L15B43016310          |