



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO DYNAMIQUE 16V
Colour	Silver
Year of manufacture	-
Top speed	114 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	127 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg






Internet history

Entry 2


Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	23
Listing price	View report



source: [yesauto.com](#)

**MOT history**

MOT #23	2022-09-02 11:45
MOT test number	772259806200
Result	✓ Passed
Next expiry date	2023-09-01

MOT #22	2022-09-02 09:12
MOT test number	226785371881
Result	✗ Failed
<div><div>Fail</div>Windscreen washer provides insufficient washer liquid (3.5 (a))</div> <div><div>Fail</div>Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))</div> <div><div>Fail</div>Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))</div>	

MOT #21	2021-08-23 15:48
MOT test number	168016515180
Result	✓ Passed
<div><div>Advice</div>Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))</div> <div><div>Advice</div>Rear exhaust mount weak</div> <div><div>Advice</div>Handbrake high</div> <div><div>Advice</div>Offside Rear tyre outer wall cut</div>	

**MOT #20**

2021-08-23 09:01

MOT test number

276923911020

Result

✗ Failed

- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- Fail** Brake fluid contaminated (1.8 (a))
- Advice** Handbrake high
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Rear exhaust mount weak
- Fail** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Horn not working (7.7 (a) (ii))
- Fail** Headlamp aim too high n/s & o/s (4.1.2 (a))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Coolant low
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear tyre outer wall cut

MOT #19

2020-08-24 07:16

MOT test number

964838176776

Result

✓ Passed

**MOT #18**

2020-08-13 09:29

MOT test number

664430184424

Result**✗ Failed****Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Fuel Pipe/s corroded**Fail** Central Front Windscreen washer not working (3.5 (a))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #17**

2019-10-02 12:09

MOT test number

588885422426

Result**✓ Passed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #16**

2019-09-30 12:32

MOT test number

744966596127

Result**✗ Failed****Fail** Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #15**

2018-09-28 13:56

MOT test number

979808882171

Result

✓ Passed

- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Shock absorbers has slight external damage to the casing x2 (5.3.2 (b))
- Advice** Rear Brake pipe corroded, covered in grease or other material all rear (1.1.11 (c))
- Minor** Offside Front Brake hose slightly damaged (1.1.12 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14

2018-09-28 07:28

MOT test number

621940029414

Result

✗ Failed

- Advice** Rear Shock absorbers has slight external damage to the casing x2 (5.3.2 (b))
- Minor** Offside Front Brake hose slightly damaged (1.1.12 (b) (i))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material all rear (1.1.11 (c))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))



MOT #13	2017-07-04 13:51
MOT test number	605666415223
Result	✓ Passed
Advice	Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #12	2017-07-04 13:51
MOT test number	159278987565
Result	✗ Failed
Advice	Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Pass with rectification	Offside Front Anti-lock braking system component inappropriately repaired (3.4.4)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #11	2016-04-19 15:17
MOT test number	223052418498
Result	✓ Passed

MOT #10	2016-04-15 15:41
MOT test number	927445020153
Result	✗ Failed
Fail	Nearside Front front brake binding (3.7.B.1)
Fail	Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
Fail	Front Brakes imbalanced across an axle (3.7.B.5b)
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #9** 2015-04-17 15:41**MOT test number** 829407705152**Result** ✓ Passed**MOT #8** 2015-04-16 16:42**MOT test number** 295246905129**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Headlamp not working on main beam (1.7.5a)**Fail** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**Fail** Nearside Front Headlamp not working on main beam (1.7.5a)**Fail** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**MOT #7** 2014-07-09 11:44**MOT test number** 836740694173**Result** ✓ Passed**MOT #6** 2013-07-20 11:43**MOT test number** 546311903224**Result** ✓ Passed**MOT #5** 2013-07-12 11:20**MOT test number** 138113993149**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Front Lower Ball joint has excessive play (2.2.B.1f)**Fail** Nearside Front Lower Ball joint has excessive play (2.2.B.1f)

**MOT #4** 2012-06-30 10:47**MOT test number** 916332982184**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-07-22 16:07**MOT test number** 966443801298**Result** ✓ Passed**MOT #2** 2010-10-25 09:50**MOT test number** 333108290494**Result** ✓ Passed**MOT #1** 2010-10-25 09:50**MOT test number** 813288390200**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-09-25
Last registration	2022-09-02
Complete history	See info



Registration #1	2007-09-25	27 mi
Registration #2	2010-10-25	33.904 mi
Registration #3	2011-07-22	35.038 mi
Registration #4	2012-06-30	41.245 mi
Registration #5	2013-07-12	48.187 mi
Registration #6	2013-07-20	48.320 mi
Registration #7	2014-07-09	54.603 mi
Registration #8	2015-04-16	58.291 mi
Registration #9	2015-04-17	58.291 mi
Registration #10	2016-04-15	64.994 mi
Registration #11	2016-04-19	64.998 mi
Registration #12	2017-07-04	71.311 mi
Registration #13	2017-07-04	71.311 mi
Registration #14	2018-05-22	75.277 mi
Registration #15	2018-05-22	75.277 mi
Registration #16	2018-05-22	75.277 mi
Registration #17	2018-05-22	75.277 mi
Registration #18	2018-05-22	75.277 mi
Registration #19	2018-05-22	75.277 mi
Registration #20	2018-05-22	75.277 mi
Registration #21	2018-05-22	75.277 mi
Registration #22	2018-05-22	75.277 mi
Registration #23	2018-05-22	75.277 mi
Registration #24	2018-05-22	75.277 mi
Registration #25	2018-05-22	75.277 mi



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1940 mm
Height	1496 mm
Length	3986 mm
Wheel base	2575 mm
Kerb weight	1135 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	D078306
---------------	---------